



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNM 3926A

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER RH TOP GARNISH (SN)	TO REPAIR SEE LABOUR	\$320.00	\$0.00
1	R/R WHEEL GARNISH (SN)	CUT	\$300.00	\$300.00
			\$620.00	\$300.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE REAR GARNISH OUT TO FACILITATE REPLACEMENT OF PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER RH TOP GARNISH		\$300.00	\$280.00
	TO RESPRAY PAINTING		\$500.00	\$400.00
	TO REPAIR R/R WHEEL RIM		\$500.00	\$100.00
			\$1,300.00	\$780.00
GRAND TOTAL			\$1,920.00	\$1,080.00
RECOMMENDED COST OF REPAIRS				\$1,080.00
Report Ref No: CS/FCI24080350/Uqp3				

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.