

Not Authenticated
11/10/2024 \$10,550

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHD93155

AAD2408-055

Vehicle No.:

Chassis No.:

Co UEN.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

16 AUG 2024

SHD93155

JTDKB3FU203073173

200303878K

TOYOTA

PRIUS

11/4/2024

GBH7160J/CHINA

26/10/2018

PART

LIST

- 1 COVER, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 SEAL, REAR BUMPER SIDE, RH
- 1 SEAL, REAR BUMPER SIDE, LH
- 1 GUARD, REAR BUMPER, CENTER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 FILLER, REAR BUMPER EXTENSION, RH
- 1 FILLER, REAR BUMPER EXTENSION, LH
- 1 COVER, FLOOR UNDER, RH
- 1 COVER, FLOOR UNDER, LH
- 1 COVER, REAR FLOOR
- 1 COVER, BACK DOOR TRIM
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 LENS & BODY, REAR COMBINATION LAMP, RH (UPPER)
- 1 LENS AND BODY, REAR LAMP, RH
- 1 COVER, REAR COMBINATION LAMP, RH
- 1 PANEL SUB-ASSY, BACK DOOR
- 1 GLASS, BACK WINDOW FIX
- 1 DAM, WINDOW GLASS ADHESIVE
- 1 SPOILER SUB-ASSY, REAR
- 1 SEAL, REAR SPOILER
- 1 LAMP SET, STOP CENTER
- 1 PANEL ASSY, DECK TRIM SIDE, RH
- 1 BOARD ASSY, BACK DOOR TRIM
- 1 PANEL ASSY, BACK DOOR TRIM, UPPER
- 1 BOARD, BACK DOOR TRIM
- 1 STAY ASSY, BACK DOOR, LH
- 1 STAY ASSY, BACK DOOR, RH

\$	Bu	558.39	—
\$	Ph	19.43	—
\$	hit	148.58	—
\$	Di	148.58	—
\$	Lu	111.41	X
\$	Lu	111.41	X
\$	Ry	726.92	—
\$	Ry	419.90	—
\$	Lu	155.72	X
\$	mgum	155.72	—
\$	hit	220.50	—
\$	hit	304.92	—
\$	hit	290.43	—
\$	Lu	31.50	X
\$	Ry	824.46	—
\$	Gr	570.15	—
\$	CM	634.73	—
\$	Lu	81.48	X
\$	Ry	1,443.86	—
\$	Photograph	957.39	—
\$	Lu	65.21	—
\$	CM	1,986.92	—
\$	Lu	21.32	—
\$	CM	242.34	—
\$	Lu	448.98	X
\$	Di	326.76	—
\$	Lu Ry	65.73	X
\$	Bu	284.55	—
\$	Lu	305.66	X
\$	Lu	305.66	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHD93155

- 1 HINGE ASSY, BACK DOOR, LH
- 1 HINGE ASSY, BACK DOOR, RH
- 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
- 1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2
- 1 PLATE, BACK DOOR NAME, NO.1
- 1 ORNAMENT SUB-ASSY, BACK DOOR
- 1 COVER, FRONT BUMPER
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 SUPPORT, FRONT BUMPER SIDE, LH
- 1 SUPPORT, FRONT BUMPER SIDE, RH
- 1 STAY SUB-ASSY, FRONT BUMPER, LH
- 1 STAY SUB-ASSY, FRONT BUMPER, RH
- 1 COVER, FRONT BUMPER HOLE, LH
- 1 COVER, FRONT BUMPER HOLE, RH
- 1 GRILLE, RADIATOR, LOWER NO.1
- 1 GRILLE SUB-ASSY, RADIATOR
- 1 EMBLEM ASSY, RADIATOR GRILLE
- 1 BRACKET, FRONT BUMPER EXTENSION MOUNTING

\$	Dis	77.18	✓
\$	Dis	77.18	✓
\$	CM	1,171.38	✓
\$	na	68.88	✓
\$	na	68.88	✓
\$	na	90.30	✓
\$	Bu	653.31	✓
\$	su	100.17	X
\$	h	902.16	X
\$	Dis	100.49	✓
\$	h	100.49	X
\$	h	59.85	X
\$	h	59.85	X
\$	h	37.07	X
\$	h	37.07	X
\$	Dis	214.41	✓
\$	CM	436.38	✓
\$	na	114.98	✓
\$	h	130.31	X
TOTAL \$ 16,468.83			
25%	\$	4,117.21	
	\$	12,351.62	

SPECIAL NETT

- 1 FRT BUMPER CLIP
- 1 FRT NUMBER PLATE WITH MOULDING
- 1SET PARKING AID
- 1 REAR BUMPER CLIP
- 1 REAR RH BUMPER RETAINER CLIP
- 1 REAR SPOILER CLIP
- 1 REAR NUMBER PLATE
- 1 REAR TAIL LAMP CLIP
- 1 END PANEL INNER TRIM CLIP
- 1 BOOT STICKER TRANSCAB
- 1 BOOT STICKER TEL NO
- 1 REAR BUMPER PROTECTOR
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

\$	na	65.00	605N
\$	h	180.00	455N
\$	mis	700.00	2205N
\$	na	65.00	605N
\$	na	65.00	X
\$	na	65.00	✓
\$	su	180.00	X
\$	na	65.00	✓
\$	na	60.00	✓
\$	na	100.00	305N
\$	na	100.00	305N
\$	na	180.00	305N
\$	na	150.00	805N
\$	na	200.00	✓
\$	na	130.00	305N
TOTAL \$ 2,305.00			

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHD9315S**AAD2408-055**

TOTAL PARTS	\$	14,656.62
--------------------	-----------	------------------

LABOUR

To rust-proofing of the affected areas.	\$	600.00	30d
Putty and spray painting of the affected portion.	\$	1,200.00	110d
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,000.00	80d
To transfer of tailgate fittings and conduct water seepage test.	\$	170.00	60d
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	100d
To reinstall rear bumper parking sensor.	\$	170.00	50d
To check steering geometry and computer wheel alignment	\$	220.00	nn X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	nn X

TOTAL	\$	4,910.00
--------------	-----------	-----------------

OVERALL TOTAL	\$	19,566.62
----------------------	-----------	------------------

8days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: