

ASS. REC. BY:

REF:

0721

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$27,744

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

08

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1

Got BZ

19/8

L1 Rep @ 10,550p Cahn

Veh No:

SHD 9315P

Yr Regn:

10.18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Tag Prius

C.C.

1798

Colour

M.P. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

433503

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB31F-U 203073173

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

Sai/Un

195/65R15

R: Wanli

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

15/8/24

D.O.I.

16/8/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS. SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

Not Authenticated
L1Ry \$10,550k

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHD93155

AAD2408-055

Vehicle No.:

Chassis No.:

Co UEN.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

16 AUG 2024

SHD93155

JTDKB3FU203073173

200303878K

TOYOTA

PRIUS

11/4/2024

GBH7160J/CHINA

26/10/2018

PART	LIST
1 COVER, REAR BUMPER	\$ Bu 558.39 —
1 COVER, REAR BUMPER, LOWER	\$ this 19.43 —
1 RETAINER, REAR BUMPER SIDE, RH	\$ hit 148.58 —
1 RETAINER, REAR BUMPER SIDE, LH	\$ Ory 148.58 —
1 SEAL, REAR BUMPER SIDE, RH	\$ In 111.41 X
1 SEAL, REAR BUMPER SIDE, LH	\$ In 111.41 X
1 GUARD, REAR BUMPER, CENTER	\$ Bz 726.92 —
1 REINFORCEMENT SUB-ASSY, REAR BUMPER	\$ Bz 419.90 —
1 FILLER, REAR BUMPER EXTENSION, RH	\$ In 155.72 X
1 FILLER, REAR BUMPER EXTENSION, LH	\$ mgum 155.72 —
1 COVER, FLOOR UNDER, RH	\$ hit 220.50 —
1 COVER, FLOOR UNDER, LH	\$ hit 304.92 —
1 COVER, REAR FLOOR	\$ hit 290.43 —
1 COVER, BACK DOOR TRIM	\$ In 31.50 X
1 PANEL SUB-ASSY, BODY LOWER BACK	\$ Bz 824.46 —
1 LENS & BODY, REAR COMBINATION LAMP, RH (UPPER)	\$ GT 570.15 —
1 LENS AND BODY, REAR LAMP, RH	\$ CM 634.73 —
1 COVER, REAR COMBINATION LAMP, RH	\$ In 81.48 X
1 PANEL SUB-ASSY, BACK DOOR	\$ Bz 1,443.86 —
1 GLASS, BACK WINDOW FIX	\$ Shattered 957.39 —
1 DAM, WINDOW GLASS ADHESIVE	\$ Ma 65.21 —
1 SPOILER SUB-ASSY, REAR	\$ CM 1,986.92 —
1 SEAL, REAR SPOILER	\$ Ma 21.32 —
1 LAMP SET, STOP CENTER	\$ CM 242.34 —
1 PANEL ASSY, DECK TRIM SIDE, RH	\$ In 448.98 X
1 BOARD ASSY, BACK DOOR TRIM	\$ Di's 326.76 —
1 PANEL ASSY, BACK DOOR TRIM, UPPER	\$ In B 65.73 X
1 BOARD, BACK DOOR TRIM	\$ Bz 284.55 —
1 STAY ASSY, BACK DOOR, LH	\$ In 305.66 X
1 STAY ASSY, BACK DOOR, RH	\$ In 305.66 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

AAD2408-055**SHD93155**

- 1 HINGE ASSY, BACK DOOR, LH
- 1 HINGE ASSY, BACK DOOR, RH
- 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
- 1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2
- 1 PLATE, BACK DOOR NAME, NO.1
- 1 ORNAMENT SUB-ASSY, BACK DOOR
- 1 COVER, FRONT BUMPER
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 SUPPORT, FRONT BUMPER SIDE, LH
- 1 SUPPORT, FRONT BUMPER SIDE, RH
- 1 STAY SUB-ASSY, FRONT BUMPER, LH
- 1 STAY SUB-ASSY, FRONT BUMPER, RH
- 1 COVER, FRONT BUMPER HOLE, LH
- 1 COVER, FRONT BUMPER HOLE, RH
- 1 GRILLE, RADIATOR, LOWER NO.1
- 1 GRILLE SUB-ASSY, RADIATOR
- 1 EMBLEM ASSY, RADIATOR GRILLE
- 1 BRACKET, FRONT BUMPER EXTENSION MOUNTING

\$	Dis	77.18	—
\$	Dis	77.18	—
\$	CM	1,171.38	—
\$	Na	68.88	—
\$	Na	68.88	—
\$	Na	90.30	—
\$	Bu	653.31	✓
\$	Sn	100.17	X
\$	R	902.16	X
\$	Dis	100.49	—
\$	Ln	100.49	X
\$	Ln	59.85	X
\$	Ln	59.85	X
\$	Ln	37.07	X
\$	Ln	37.07	X
\$	Dis	214.41	—
\$	CM	436.38	—
\$	Na	114.98	—
\$	R	130.31	X
TOTAL \$		16,468.83	
25% \$		4,117.21	
\$		12,351.62	

SPECIAL NETT

- 1 FRT BUMPER CLIP
- 1 FRT NUMBER PLATE WITH MOULDING
- 1SET PARKING AID
- 1 REAR BUMPER CLIP
- 1 REAR RH BUMPER RETAINER CLIP
- 1 REAR SPOILER CLIP
- 1 REAR NUMBER PLATE
- 1 REAR TAIL LAMP CLIP
- 1 END PANEL INNER TRIM CLIP
- 1 BOOT STICKER TRANSCAB
- 1 BOOT STICKER TEL NO
- 1 REAR BUMPER PROTECTOR
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

\$	Na	65.00	605N
\$	R	180.00	455N
\$	mis	700.00	2205N
\$	Na	65.00	605N
\$	Na	65.00	X
\$	Na	65.00	—
\$	Sn	180.00	X
\$	Na	65.00	—
\$	Na	60.00	—
\$	Na	100.00	305N
\$	Na	100.00	305N
\$	Na	180.00	305N
\$	Na	150.00	805N
\$	Na	200.00	—
\$	Na	130.00	305N
TOTAL \$		2,305.00	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHD9315S**AAD2408-055****TOTAL PARTS \$ 14,656.62****LABOUR**

To rust-proofing of the affected areas.	\$	600.00	301
Putty and spray painting of the affected portion.	\$	1,200.00	11001
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,000.00	8001
To transfer of tailgate fittings and conduct water seepage test.	\$	170.00	601
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	1001
To reinstall rear bumper parking sensor.	\$	170.00	501
To check steering geometry and computer wheel alignment	\$	220.00	~ ~ X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	~ ~ X

TOTAL \$ 4,910.00**OVERALL TOTAL \$ 19,566.62***8 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	878K

Vehicle Details

Vehicle No.:	SHD9315S
Vehicle to be Exported:	Yes
Intended Deregistration Date:	15 Aug 2024
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2B44795
Chassis No.:	JTDKB3FU203073173
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	26 Oct 2018
First Registration Date:	26 Oct 2018
Transfer Count:	0
Actual ARF Paid:	\$14,247.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Oct 2026
PARF Rebate Amount:	\$9,972.00

Intended COE Rebate Details

COE Expiry Date:	25 Oct 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$24,228.00
COE Rebate Amount:	\$6,643.00
Total Rebate Amount:	\$16,615.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be deregistered once the COE expires, or when it reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 15 Aug 2024

OK