

WE GARAGE

11 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit, Singapore 417883

wegarage@consultant.com

Mobile : +65 9009 6622

LKK Auto Consultants hereby notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, to the insurance surveyor
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

not Authorized
rec
23/8/24
1/5 @ 1700
2 days
telephone

23 August 2024

REG NO. : GY 3663 C
MAKE/MODEL : TOYOTA DYNA

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Front headlamp 11	\$ 1,180.50 X
1	Front bumper 11	\$ 782.80 X
1	Front bumper bracket 11	\$ 198.00 X
1	Front door - L/H 20/30/40	\$ 1,799.20 1,868.60 ✓
1	Front door checker 11	\$ 131.80 X
2	Front door hinges 80	\$ 157.00 X
1	Front door glass outer moulding 11	\$ 148.90 X
1	Front door inner board 11	\$ 897.50 X
1	Front door lettering sticker rec	\$ 45.00 ✓
1	Front door regulator 30/40	\$ 295.70 ✓
1	Front door regulator motor 80	\$ 509.40 X
1	Front door rubber 11	\$ 190.10 X
		\$ 6,405.30
	Less 25%	\$ 1,601.33
		\$ 4,803.98
<u>SPECIAL NETT ITEMS</u>		
1	Front door lettering sticker Reg 11	\$ 45.00 X
1	Front door company sticker rec	\$ 280.00 160 S/W
		\$ 325.00
<u>LABOUR CHARGES</u>		
1	To check wiring and reset headlamps focusing.	\$ 80.00 20
2	To remove, refit door fittings and replace damaged parts, transfer to new door	\$ 200.00 60
3	To apply undercoating.	\$ 180.00 30
4	Panel beating.	\$ 120.00 60
5	To re-spray painting on the affected areas.	\$ 1,600.00 200
		\$ 2,180.00

GRAND TOTAL :

Page 1 of 1

P-2138.90

252

1604.93

160

370

2134.93

\$ 7,308.98