

**LKK Auto Consultants Pte Ltd**51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.

19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24080356/Unh3e2
75 BRAS BASAH ROAD	Date:	27/08/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBE 6002E	Veh. Inspected	GY 3663C
Policy No.	-	Coverage	0
Claim No.	MT/1290911-002	Excess	\$0.00
Assign From	RAJESWARY	Assign Date	22/08/2024

2. Vehicle Details

Make & Model	TOYOTA DYNA (M)	C.C	2982
Engine No.	1KD2764334	Year of Reg.	28/03/2018
Chassis No.	JTFAT35Y10K209500	Colour	SILVER
Odometer	67699 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/75R15	AGILIS	6
L/H Front Tyre	195/75R15	AGILIS	6
R/H Rear Tyre	155R12 (D)	CONDOR	6/6
L/H Rear Tyre	155R12 (D)	CONDOR	6/6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/08/2024	Inspection Date	23/08/2024 (10:06)
Survey held at	WE GARAGE - 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days