



VAG Singapore Pte Ltd
 48 Toh Guan Road East
 #05-136, Enterprise Hub
 Singapore 608586

Vehicle Repair Estimate

Tel: 6267 9916
 Fax: 6267 9313
 www.avantage.sg

Date : 20-Aug-2024

Vehicle Num : SLK1293P

Make/Model : B.M.W. / 318i LED NAV

Chassis No : WBA8E36080NU33000

S/N	PARTS	QTY	PRICE	TOTAL
1	Rear door Rh <i>repair</i>	1	\$ 1,815.32	\$ 1,815.32
2	Rear fender Rh <i>repair</i>	1	\$ 608.45	\$ 608.45
3	Sport rim <i>Xm</i>	1	\$ 2,970.64	\$ 2,970.64
4	Rocket panel Rh <i>Xm</i>	1	\$ 1,183.55	\$ 1,183.55
Total Parts				\$ 6,577.96
LESS 5%				\$ 328.90
TOTAL AMOUNT				\$ 6,249.06
MISCELLANEOUS ITEM				
1	Sunderies		\$ 50.00	\$ 20 50.00
2	Rivet <i>Xm</i>	12	\$ 4.50	\$ Mx 54.00
LABOUR				
1	To remove and refitting rear fender Rh, rear door Rh, rocket panel Rh and each other.		\$ 1,280.00	\$ 400 1,280.00
2	Surface preparation, spray paint and polish rear fender Rh, reardoor Rh, rocket panel Rh and other affected areas.	<i>900</i>	\$ 1,000.00	\$ 500 1,000.00
3	To perform diagnostic check		\$ 80.00	\$ Xm 80.00
TOTAL				\$ 2,414.50
GST 9%				\$ 784.18
GRAND TOTAL				\$ 9,497.24

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

900
~~*20*~~
~~*920*~~

Ramal
 Hg 900 100 68
 3 days
 P/P
 23/08/24
 Res after repair