



NOT WITHIN  
 11 Day @ 1150h  
 Resurvey After Paint

6453 4730  
 6457 1931  
 enquiry@sh-motor.com

WORKSHOP  
 160 Sin Ming Drive  
 #07-02 Sin Ming AutoCity  
 Singapore 575722

S&H Motor Pte Ltd  
 Co. Reg. No. : 198701322K  
 GST Reg. No.: M2-0076269-0

M/s First Capital Insurance Ltd  
 36 Robinson Road #16-01  
 City House  
 Singapore 068877

File No : SH/2024/0119  
 Date : 20/8/2024

Estimated cost of repair for vehicle no: SNF8166E Hyundai Avante  
 Accident involving vehicle no: SNF8166E & SHC2080U On 19/8/2024

Description	Quantity	List Price
Rear bumper <i>520.80</i>	1	\$ <i>M/C</i> 755.00 <i>✓</i>
Rear bumper side retainer rh	1	\$ <i>M</i> 36.90 <i>✓</i>
Rear bumper reverse sensor	1	\$ <i>R</i> 202.00 <i>X</i>
Rear lamp rh <i>590.80</i>	1	\$ <i>M/C</i> 788.00 <i>✓</i>
		\$ 1,781.90
	LESS <i>10%</i> <i>208</i>	\$ 178.19
		\$ 1,603.71

**Special Nett**

Rear bumper clip	1	\$ <i>M</i> 40.00 <i>✓</i>
------------------	---	----------------------------

**Labour**

To dismantle, replace, cut, weld, knock out dents to straighten accident damaged parts.	\$	300.00 <i>200</i>
Remove & refix/replace rear bumper reverse sensor & conduct distance safety setting	\$	70.00 <i>50</i>
Wiring /bulb checking/focusing	\$	30.00 <i>15</i>
To putty & spray paint accident damaged parts and adjacent panels	\$	400.00 <i>220</i>
	\$	2,443.71

NOT WITHIN  
 11 Day @  
 Resurvey After Paint  
 2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: