

李 汽 车 贸 易

GST REG NO. 201918537M

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 13-Jun-24

Estimate no.

1408

Plate No. FBR2111G

Model. YAMAHA R15 V3

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	FORK ALIGNMENT <i>17</i>	\$ 250.00	X	
2	STEERING CONE <i>17</i>	\$ 180.00	X	
3	FRONT PANEL COVER <i>C27</i>	\$ 200.00	✓	
4	MIRROR LEFT <i>m.s</i>	\$ <i>90</i> 150.00	✓	
5	FRONT SIGNAL LIGHT <i>CUT</i>	\$ <i>80</i> 120.00	✓	
6	HANDLE BAR LEFT <i>SVC</i>	\$ 280.00	X	
7	HANDLE BALANCER <i>C27</i>	\$ <i>35</i> 80.00	✓	
8	CLUTCH LEVER <i>C27</i>	\$ <i>118</i> 120.00	✓	
9	IU UNIT <i>17</i>	\$ 155.80	X	
10	FUEL TANK COVER LEFT <i>C27</i>	\$ 250.00	✓	
11	FUEL TANK COVER RIGHT <i>12</i>	\$ 250.00	X	
12	GEAR PEDAL <i>C27</i>	\$ <i>148</i> 180.00	✓	
13	SEAT <i>T.V.A</i>	\$ <i>166</i> 200.00	✓	
14	SEAT UNDER COVER LEFT <i>CUT</i>	\$ 180.00	✓	
15	REAR FAIRING COVER LEFT <i>CUT</i>	\$ <i>102</i> 220.00	✓	
16	SPRAY COVERSET	\$ 500.00	350	
17	LABOUR	\$ 500.00	320	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Less 10% \$ 381.58
 \$ 3,815.80
 Sub Total : \$ 3,434.22
 GST 9% \$ 309.08
 Total: \$ 3,743.30

Estimate given are base on visible damages ONLY before dismantling of the vehicle

This is computer generated no signature is required.

*not Auland
 full
 money
 18/6/24
 2/5 \$1600/
 cheap to the top
 3 days*

*p-1467
 102
 1388.30
 670
 2008.3
 226
 1656.*