



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO FBR 2111G

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FORK ALIGNMENT	NOT NECESSARY	\$250.00	\$0.00
1	STEERING CONE	NOT NECESSARY	\$180.00	\$0.00
1	FRONT PANEL COVER	CUT	\$200.00	\$200.00
1	MIRROR LEFT	MISSING	\$150.00	\$90.00
1	FRONT SIGNAL LIGHT	CUT	\$120.00	\$80.00
1	HANDLE BAR LEFT	SERVICEABLE	\$280.00	\$0.00
1	HANDLE BALANCER	CUT	\$80.00	\$35.00
1	CLUTCH LEVER	CUT	\$120.00	\$118.00
1	IU UNIT	NOT NECESSARY	\$155.80	\$0.00
1	FUEL TANK COVER LEFT	CUT	\$250.00	\$250.00
1	FUEL TANK COVER RIGHT	TO REPAIR SEE LABOUR	\$250.00	\$0.00
1	GEAR PEDAL	CUT	\$180.00	\$148.00
1	SEAT	TORN	\$200.00	\$166.00
1	SEAT UNDER COVER LEFT	CUT	\$180.00	\$180.00
1	REAR FAIRING COVER LEFT	CUT	\$220.00	\$220.00
	LESS 10.00% DISCOUNT		(\$281.58)	(\$148.70)
			\$2,534.22	\$1,338.30

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	SPRAY COVERSET		\$450.00	\$350.00
	LABOUR. INCLUSIVE OF THE REPAIR OF FUEL TANK COVER RIGHT		\$450.00	\$320.00
			\$900.00	\$670.00

GRAND TOTAL		\$3,434.22	\$2,008.30
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$1,600.00
Report Ref No: CS/FCI24060119/Unh3			



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser