

MS CAR AUTO P E LTD

8 KAKI BUKIT AVENUE 4 #01-07 PREMIE @KAKI BUKIT
SINGAPORE 415875

TO	: CHINA TAIPING	DATE	22/8/2024
VEHICLE NO	: YM7172B (2007)	<i>Hui Rong</i>	
VEHICLE MODEL	: MITSUBISHI FUSO		
CHASSIS NO	: FE83BEA10125		

CLAIM DETAILS: PARTS

	ITEMS
1	REAR NUMBER PLATE LAMP <i>Graced</i>
2	REAR NUMBER PLATE BRACKET <i>Best</i>
3	REAR CHASSIS CROSSMEMBER <i>Repis</i>
4	TAILLAMP <i>Lit ut</i>
5	TAILLAMP PANEL <i>Lit Best</i>
6	REAR STOPPER BRACKET <i>Lit Best</i>
7	TAILGATE <i>Dented</i>
8	TAILGATE HINGE <i>1 piece and</i>
9	TAILGATE LOWER PANEL <i>Repis</i>

QTY	UNIT PRICE	TOTAL
1	\$ 72.00	\$ 72.00
1	\$ 95.00	\$ 95.00
1	\$ 2,641.00	\$ 2,641.00
2	\$ 285.00	\$ 570.00
2	\$ 163.00	\$ 326.00
2	\$ 182.00	\$ 364.00
1	\$ 2,847.00	\$ 2,847.00
4	\$ 128.00	\$ 512.00
1	\$ 1,824.00	\$ 1,824.00

TOTAL PRICE: \$ 9,251.00
SS 25% \$ 2,312.75
JB TOTAL PRICE: \$ 6,938.25

SPECIAL NETT ITEMS

	ITEMS
1	REAR NUMBER PLATE <i>Best</i>
2	REAR CRASH BAR <i>Best</i>
3	REAR HORIZONTAL STEP PANEL <i>Dented</i>
4	REAR STOPPER <i>Lit ut</i>

QTY	UNIT PRICE	TOTAL
1	\$ 30.00	\$ 30.00
1	\$ 1,300.00	\$ 1,300.00
1	\$ 800.00	\$ 800.00
2	\$ 40.00	\$ 80.00
TOTAL:		\$ 2,210.00

LABOUR

	JOB
1	PANEL BEATING, REMOVE AND REFIT PARTS
2	SPRAY PAINTING TO AFFECTED AREA
3	WIRING CHECK
4	TO APPLY TUFF COAT

TOTAL:

PRICE	ADJUSTED COST	APPROVED
1,000.00	<i>600</i>	
800.00	<i>400</i>	
50.00	<i>30</i>	
150.00	<i>x</i>	
TOTAL:		2,000.00

ESTIMATE REPORT

TOTAL PARTS COST: \$ 9,148.25
TOTAL LABOUR COST: \$ 2,000.00
TOTAL REPAIR COST: \$ 11,148.25

TOTAL REPAIR COST: hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

total: 5001.25

L/S: 4K

04 Days

4K

1030