

Kok Wang Car Grooming
1 Soon Lee Street #06-40 Pioneer Centre
Singapore 627605

Hp: 91839633 E-mail: vanong@gmail.com

1948.64

360.00

1050.00

3358.64

20%

2686.91

45 - \$2700 / 4 days

ESTIMATE REPORT

Vehicle Number : SMP287B

Make And Model : Honda Shuttle Hybrid

Date of Accident : 13 August 2024

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

S/No	Parts	Signature:	QTY	Unit Price	List Price
1	Front bumper for		1		\$ 1,050.60 x R
2	Front bumper retainer LH ? XAN		1	RASEL	\$ 15.40 X
3	Front bumper side cover LH XAN		1	Hp 90010068	\$ 33.20 X
4	Front bumper fog lamp LH X AN		1		\$ 287.80 X
5	Front bumper fog lamp cover LH XAN		1	4 days	\$ 45.10 X
6	Front fender LH repair		1	4 days	\$ 435.20 X R
7	Front fender bracket LH XAN		1	45	\$ 49.50 X
8	Front fender inner shield LH XAN		1		\$ 120.50 ✓
9	Front fender 'HYBRID' emblem LH XAN		1		\$ 65.30 ✓
10	Front headlamp LH son		1	23/09/24	\$ 2,315.60 2250
11	Front headlamp lower bracket LH XAN		1		\$ 45.30 X
12	Front shock absorber LH XAN		1	Reen after	\$ 480.00 X
13	Front knuckle arm LH ? X AN		1	repair	\$ 395.00 X
14	Front knuckle arm bearing LH ? XAN		1		\$ 184.80 X
15	Front lower arm LH X AN		1		\$ 355.00 X
16	Front stabilizer link LH XAN		1		\$ 56.80 X
					\$ 5,935.10
Less 20%					\$ 1,187.02
Total					\$ 4,748.08

2435.80

20%

1948.64

Special Nett Item

1	Front bumper clips XAN	1 set	\$ 30	60.00
2	Front fender inner shield clips LH XAN	1 set	\$ 30	60.00
3	Front sport rim LH 982	1 pc	\$ 300	450.00
4	Front tyre LH XAN	1 pc	\$ X	300.00
Total			\$ 870.00	

Labour & Misc Charges

- To dismantle, replace & panel beating affected portion.
- To spray paint on affected portion.
- To remove/replace/reinstall front under carriage components.
- To apply anti-rust on affected areas.
- To check wiring for front portion.
- To perform system diagnostic & reset ECU system.

1050

\$ 400	1,000.00
\$ 400	800.00
\$ 80	300.00
\$ 40	60.00
\$ 30	60.00
\$ 100	300.00
Total	\$ 2,520.00

Grand Total : \$ 8,138.08