



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS SOMPO INSURANCE SINGAPORE PL	Ref:	CS/SMO24080363/Unp3
50 RAFFLES PLACE #03-03	Date:	04/09/2024
SINGAPORE LAND TOWER SINGAPORE 048623	Code:	SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	EG 9669R	Veh. Inspected	SMZ 9824P
Policy No.	D23MTPV01014837	Coverage	0
Claim No.	CMTD2401400/JYC	Excess	\$0.00
Assign From	JIA YI	Assign Date	22/08/2024

2. Vehicle Details

Make & Model	MAZDA CX-5 (A)	C.C	1998
Engine No.	PE31686659	Year of Reg.	27/05/2021
Chassis No.	JM6KF2W7AM0676690	Colour	BLUE
Odometer	33005 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/65R17	YOKOHAMA	6
L/H Front Tyre	225/65R17	YOKOHAMA	6
R/H Rear Tyre	225/65R17	YOKOHAMA	6
L/H Rear Tyre	225/65R17	YOKOHAMA	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/04/2024	Inspection Date	28/08/2024
Survey held at	HUP LIAN HUAT ENGINEERING WORKS - 38 DEFU LANE 9, DEFU INDUSTRIAL ESTATE, SINGAPORE 539278		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days