

HUP LIAN HUAT ENGINEERING WORKS

No.38 Defu Lane 9, Singapore 539278
 TEL: 6282 3336 (3 Lines) FAX: 6289 3336 Email: mahlian@singnet.com.sg
 GST:52832105J RCB NO:201327339E

Not Authorised
 m/c
 28/8/24
 L/S \$5000
 4 days

M/S : SOMPO INSURANCE SINGAPORE PTE LTD

50 Raffles Pl

#03-03 Singapore Land Tower,
 Singapore 048623

TEL: 6461 6555

ATTN: Motor Claim Department

Estimate No: ES1602141

Date: 22 Apr 2024

Policy No: DMPG23006775

Veh Reg No: SMZ9824P

Make/Model: MAZDA CX-5 2.0 AT
 ELEGANCE 2WD I4

Chassis No: JM6KF2W7AM0676690

Engine No: PE31686659

Reg. Date: 27/05/2021

Your Ref No: CHUA CHENG LIANG

Claim Type: Third Party

Accident Date: 22/04/2024

TP Veh Reg No: EG9669R

Estimate Repair Cost to Vehicle No :SMZ9824P

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
List Price				
1 Lift Gate Tailgate Body 2D	1,850.50	1 PC	1,850.50	✓
2 Lift Gate Drain Plug	64.00	1 PC	64.00	X
3 Lift Gate Bumper Rear windscreen molding	399.00	1 PC	399.00	✓
4 Bumper Cover Protector Tailgate outer garnish	453.20	1 PC	453.20	✓
5 Bumper Fastener	12.60	1 PC	12.60	X
6 Lift Gate Hinge	463.10	1 PC	463.10	X
7 Lift Gate Weather Strip	398.20	1 PC	398.20	X
8 Upper Weather Strip	539.50	1 PC	539.50	X
9 Upper Weather Strip Tailgate inner trim board	524.10	1 PC	524.10	✓
10 Lift Gate Windscreen	2,351.00	1 PC	2,351.00	X
11 Lift Gate Power Cylinder Tailgate inner lock	693.50	1 PC	693.50	✓
12 Lift Gate Support Strut	315.90	1 PC	315.90	X
13 Lift Gate Switch	219.30	1 PC	219.30	X
14 Lock Actuator	374.50	1 PC	374.50	X
15 Warning Buzzer	264.10	1 PC	264.10	X
16 Control Module	1,365.00	1 PC	1,365.00	X
17 Pinch Sensor -LH/RH Rear bumper release sensor	411.90	2 PC	823.80	200 S/N
18 Rear Bumper	1,243.00	1 PC	1,243.00	1242-88
19 Rear Bumper Cover Cap	198.50	1 PC	198.50	✓
20 Rear Bumper Cover Protector	693.00	1 PC	693.00	X
21 Rear Bumper Cover Centre Bracket	553.90	1 PC	553.90	X
22 Tow Eye Cap	95.30	1 PC	95.30	X
23 Retainer Bracket -LH/RH	385.10	2 PC	770.20	X
24 Splash Shield -LH/RH	559.50	2 PC	1,119.00	X
25 Rear Impact Bar bumper beam	1,025.00	1 PC	1,025.00	✓
26 Rear Bumper Stay -LH/RH	213.50	2 PC	427.00	X
27 Reflector -LH/RH	399.80	2 PC	799.60	12 C
28 Filler	159.40	1 PC	159.40	X
29 Under Cover	559.50	1 PC	559.50	X
30 Bumper Cover Centre Bracket	859.30	1 PC	859.30	X
31 Lift Gate Upper Molding	550.00	1 PC	550.00	X
32 Lift Gate Upper Protector	735.50	1 PC	735.50	X
33 Lift Gate Lower Molding	550.00	1 PC	550.00	X
34 Lift Gate Lower Molding Protector	735.50	1 PC	735.50	X
35 Mount Bracket	219.50	1 PC	219.50	X
36 Trunk Mat	938.40	1 PC	938.40	X
37 Support Lower -LH/RH	615.50	2 PC	1,231.00	X

HUP LIAN HUAT ENGINEERING WORKS

No.38 Defu Lane 9 , Singapore 539278
 TEL: 6282 3336 (3 Lines) FAX: 6289 3336 Email: mahlian@singnet.com.sg
 GST:52832105J RCB NO:201327339E

M/S : SOMPO INSURANCE SINGAPORE PTE LTD

50 Raffles Pl
 #03-03 Singapore Land Tower,
 Singapore 048623

TEL: 6461 6555

ATTN: Motor Claim Department

Your Ref No: CHUA CHENG LIANG

Claim Type: Third Party

Accident Date: 22/04/2024

TP Veh Reg No: EG9669R

Estimate No: ES1602141

Date: 22 Apr 2024

Policy No: DMPG23006775

Veh Reg No: SMZ9824P

Make/Model: MAZDA CX-5 2.0 AT
 ELEGANCE 2WD I4

Chassis No: JM6KF2W7AM0676690

Engine No: PE31686659

Reg. Date: 27/05/2021

Estimate Repair Cost to Vehicle No :SMZ9824P

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
38 Side Trim -LH/RH	^ ^ 1,650.10	2 PC	3,300.20 X	
39 Sill Plate	^ ^ 773.40	1 PC	773.40 X	
40 Tail Lamp Assy -LH/RH	^ ^ 930.40	2 PC	1,860.80 X	
41 Tail Lamp Protector -LH/RH	^ ^ 511.50	2 PC	1,023.00 X	
42 Support Bracket -LH/RH	^ ^ 1,300.50	2 PC	2,601.00 X	
43 Support Bracket Cap -LH/RH	^ ^ 899.50	2 PC	1,799.00 X	
44 Trunk Cover End Trim	^ ^ 657.10	1 PC	657.10 X	
45 Lift Gate Side Trim	^ ^ 1,565.00	2 PC	3,130.00 X	
46 Lift Gate Lower Trim	^ ^ 1,610.50	1 PC	1,610.50 X	
47 Lift Gate Upper Trim	^ ^ 1,600.40	1 PC	1,600.40 X	
48 Trim Clips	^ ^ 8.00	7 PC	56.00 X	
		(22)	43,384.30	43,384.30
Net Price				
49 Rear Number Plate	Scn 80.00	1 PC	80.00 35 S/N	
50 Rear Number Plate Bracket	NS 50.00	1 PC	50.00 X	
			130.00	130.00
Labour				
51 Labour to dismantle lift gate & renew lift gate .	580.00	1 -	580.00 60	
52 Labour to renew & refit bumper .	480.00	1 -	480.00 X	
53 Labour to reconnect & renew tail lamp .	200.00	1 -	200.00 20	
54 Labour to reconnect reverse buzzer & all sensors .	380.00	1 -	380.00 30	
55 Labour to renew lift gate hydraulic lift gate .	580.00	1 -	580.00 X	
56 Labour to knock ,weld & renew all accident affected area .	1,800.00	1 -	1,800.00 500	
57 Labour to renew & dismantle lift gate windscreen .	480.00	1 -	480.00 120	
58 To rust proofing on all affected area .	480.00	1 -	480.00 30	
59 To spray & painting on affected area .	1,200.00	1 -	1,200.00 380	
			6,180.00	6,180.00

P-554266
 202
 4434.13
 235
 1640
 6219.13
 202
 5017

HUP LIAN HUAT ENGINEERING WORKS

No.38 Defu Lane 9 , Singapore 539278
 TEL: 6282 3336 (3 Lines) FAX: 6289 3336 Email: mahlian@singnet.com.sg
 GST:52832105J RCB NO:201327339E

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
 50 Raffles Pl
 #03-03 Singapore Land Tower,
 Singapore 048623
 TEL: 6461 6555
 ATTN: Motor Claim Department

Your Ref No: CHUA CHENG LIANG
 Claim Type: Third Party
 Accident Date: 22/04/2024
 TP Veh Reg No: EG9669R

Estimate No: ES1602141
 Date: 22 Apr 2024
 Policy No: DMPG23006775
 Veh Reg No: SMZ9824P
 Make/Model: MAZDA CX-5 2.0 AT
 ELEGANCE 2WD I4
 Chassis No: JM6KF2W7AM0676690
 Engine No: PE31686659
 Reg. Date: 27/05/2021

Estimate Repair Cost to Vehicle No :SMZ9824P

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
			Total	S\$ 49,694.30
			Add GST @ 9%	4,472.49
			Total Amount Payable	S\$ 54,166.79

TOTAL: SINGAPORE DOLLAR FIFTY FOUR THOUSAND ONE HUNDRED SIXTY SIX AND CENTS SEVENTY NINE ONLY

For HUP LIAN HUAT ENGINEERING
 WORKS

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: