

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/ SMO 24080363/4mp3**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SMT 9824Pat Workshop m/s Wipien huof

of _____

Insured: EG 9669R

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**Bal. or Market Value: \$128k.IDAC Accident Rpt: _____ Consistent?: **Yes** or **No**GIA / PR Seen: _____ Consistent?: **Yes** or **No**Est. Repairs: 4 days Res.: **Yes** or **No**Lum Sum: 20 % 3 Val.: **Yes** or **No****CA / REV / REP. / 24 HRS**120xDate: _____ Vehicle: **IN / OUT**Person Contacted: LIAISONVeh No: SMT 9824P Yr Regn: 27/05/21Type: **M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /**Truck / Trailer or CA/Make: Mazda CX-5 c.c. 1998Colour: Blue A/C: **Insured / Std / NI / NA**Sp. Reading: 33005 T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: JM6KF2W7AM*0676690Gen. Cond: **Good / Fair / Poor / Burnt**Steering: **Inorder / Jammed / Leaked / Burnt** orBrake: **Inorder / Jammed / Leaked / Burnt** orModi: **Nil / S/Rim / STD A/Rim** orTyre Size: **F:** 225/65-217**R:** _____**BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /****TOYO / YOKO** orFront 6 Rear 6

R/Bal. _____ mm R/Bal. _____ mm

L/Bal. 6 mm L/Bal. 6 mmD.O.A. 22/04/24 D.O.I. 28/8/24

Survey held at _____

Des. of Damages: **Frt / Rear / O/S / N/S / U/C / Rooftop** orReeThe **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time	Action / Instruction
<u>3/9/24</u>	<u>2/5 # 5000 in hand sign</u> <u>(Red. # 44694.30, 891.)</u>

Date/Time, File Pass to?

☐ : **Preli. Report**Days Of Repair: 4

1)

☐ : **Final Report**

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$) _____

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	120Z
Vehicle Details	
Vehicle No.:	SMZ9824P
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Aug 2024
Vehicle Make:	MAZDA
Vehicle Model:	CX-5 2.0 AT ELEGANCE 2WD I4
Primary Colour:	Blue
Manufacturing Year:	2021
Engine No.:	PE31686659
Chassis No.:	JM6KF2W7AM0676690
Maximum Power Output:	121.0 kW (162 bhp)
Open Market Value:	\$22,084.00
Original Registration Date:	27 May 2021
First Registration Date:	27 May 2021
Transfer Count:	0
Actual ARF Paid:	\$22,918.00 11459
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 May 2031
PARF Rebate Amount:	\$17,188.00
Intended COE Rebate Details	
COE Expiry Date:	26 May 2031
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$58,089.00
COE Rebate Amount:	\$39,256.00
Total Rebate Amount:	\$56,444.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 23 Aug 2024

OK


Post an Advertisement
Sell it yourself! Advertise it at just
\$72 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Reg.21Nov2019 Subaru XV 2.0i-S Eyesight AWD CVT \$86k.



Warranty With Service Till
20Nov2024 Tip-top Condition
Sunroof With Power Boot.
Direct Owner StarAd



Sort by Date Posted 20 results/page

2 vehicles



Mazda CX-5

Basic Search



Search

Price Any price Depre Any depre Reg Date 2021 to 2021 Eng Cap Any Veh Type All types
Fuel Any fuel Mileage Any OMV Any Gear Any Gear Past Owners Any
Category All categories Scheme All schemes Dealer Any Dealer Location Any Status Available



Mazda CX-5 2.0A Elegance

\$128,888

\$17,100 /yr

09-Jul-2021

1,998 cc

58,789 km

SUV

Available

1 Owner Well Maintained Agent Unit. 1 Year Warranty Provided. This Stunning Deep Crystal Blue SUV Offers A Smooth And Pleasurable Driving Experience While Maximizing Fuel Efficiency For Your Daily Need. High Loan Available With...

GMA Auto Enterprise LLP

Posted: 30-Jul-2024

PREMIUM AD



Mazda CX-5 2.0A Elegance

\$123,888

\$16,810 /yr

27-Apr-2021

1,998 cc

60,000 km

SUV

Available

Agent unit CX-5 for sale! Single owner. Call us to view this unit now. Strictly by appointment only. Bank and in house loan, including \$0 downpayment available. Thank you.

4ForWheel Pte Ltd

Posted: 19-Jun-2024

PREMIUM AD

Save this search criteria, to get email alerts whenever a match is found.

Make & Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Buy / Rent Cars

New Cars For Sale

Used Cars For Sale

Cars For Rent

Sell Your Car

Post an Ad

Sell by Bidding

Sell by Consignment

Aftermarket

Workshop Directory

Aftermarket Products

Articles

Car Reviews

Car Advice

Car News

Car Features

General

About Us

Contact Us

Careers

Site Map

Resources

COE Prices

Car Loan Calculators

Car Insurance

Car Valuation

Used Car Warranty

Bidded Carplates

Follow Sgcarmart.com



HUP LIAN HUAT ENGINEERING WORKS

No.38 Defu Lane 9, Singapore 539278
 TEL: 6282 3336 (3 Lines) FAX: 6289 3336 Email: mahlian@singnet.com.sg
 GST:52832105J RCB NO:201327339E

not authorized
 no work
 28/8/24
 1/5 \$5000
 4 days

M/S : SOMPO INSURANCE SINGAPORE PTE LTD

50 Raffles Pl
 #03-03 Singapore Land Tower,
 Singapore 048623

TEL: 6461 6555

ATTN: Motor Claim Department

Your Ref No: CHUA CHENG LIANG

Claim Type: Third Party

Accident Date: 22/04/2024

TP Veh Reg No: EG9669R

Estimate No: ES1602141

Date: 22 Apr 2024

Policy No: DMPG23006775

Veh Reg No: SMZ9824P

Make/Model: MAZDA CX-5 2.0 AT
ELEGANCE 2WD I4

Chassis No: JM6KF2W7AM0676690

Engine No: PE31686659

Reg. Date: 27/05/2021

Estimate Repair Cost to Vehicle No :SMZ9824P

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 Lift Gate Tailgate	Body 2D	1 PC	1,850.50	✓
2 Lift Gate Drain Plug	11	1 PC	64.00	X
3 Lift Gate Bumper	11	1 PC	399.00	✓
4 Bumper Cover Protector	11	1 PC	453.20	✓
5 Bumper Fastener	11	1 PC	12.60	X
6 Lift Gate Hinge	11	1 PC	463.10	X
7 Lift Gate Weather Strip	11	1 PC	398.20	X
8 Upper Weather Strip	11	1 PC	539.50	X
9 Upper Weather Strip	11	1 PC	524.10	✓
10 Lift Gate Windscreen	11	1 PC	2,351.00	X
11 Lift Gate Power Cylinder	11	1 PC	693.50	✓
12 Lift Gate Support Strut	11	1 PC	315.90	X
13 Lift Gate Switch	11	1 PC	219.30	X
14 Lock Actuator	11	1 PC	374.50	X
15 Warning Buzzer	11	1 PC	264.10	X
16 Control Module	11	1 PC	1,365.00	X
17 Pinch Sensor - LH/RH	11	2 PC	823.80	✓
18 Rear Bumper	11	1 PC	1,243.00	✓
19 Rear Bumper Cover Cap	11	1 PC	198.50	✓
20 Rear Bumper Cover Protector	11	1 PC	693.00	X
21 Rear Bumper Cover Centre Bracket	11	1 PC	553.90	X
22 Tow Eye Cap	11	1 PC	95.30	X
23 Retainer Bracket -LH/RH	11	2 PC	770.20	X
24 Splash Shield -LH/RH	11	2 PC	1,119.00	X
25 Rear Impact Bar	11	1 PC	1,025.00	✓
26 Rear Bumper Stay -LH/RH	11	2 PC	427.00	X
27 Reflector -LH/RH	11	2 PC	799.60	✓
28 Filler	11	1 PC	159.40	X
29 Under Cover	11	1 PC	559.50	X
30 Bumper Cover Centre Bracket	11	1 PC	859.30	X
31 Lift Gate Upper Molding	11	1 PC	550.00	X
32 Lift Gate Upper Protector	11	1 PC	735.50	X
33 Lift Gate Lower Molding	11	1 PC	550.00	X
34 Lift Gate Lower Molding Protector	11	1 PC	735.50	X
35 Mount Bracket	11	1 PC	219.50	X
36 Trunk Mat	11	1 PC	938.40	X
37 Support Lower -LH/RH	11	2 PC	1,231.00	X

HUP LIAN HUAT ENGINEERING WORKS

No.38 Defu Lane 9, Singapore 539278
 TEL: 6282 3336 (3 Lines) FAX: 6289 3336 Email: mahlian@singnet.com.sg
 GST:52832105J RCB NO:201327339E

M/S : SOMPO INSURANCE SINGAPORE PTE LTD

50 Raffles Pl
 #03-03 Singapore Land Tower,
 Singapore 048623

TEL: 6461 6555

ATTN: Motor Claim Department

Your Ref No: CHUA CHENG LIANG

Claim Type: Third Party

Accident Date: 22/04/2024

TP Veh Reg No: EG9669R

Estimate No: ES1602141

Date: 22 Apr 2024

Policy No: DMPG23006775

Veh Reg No: SMZ9824P

Make/Model: MAZDA CX-5 2.0 AT
 ELEGANCE 2WD I4

Chassis No: JM6KF2W7AM0676690

Engine No: PE31686659

Reg. Date: 27/05/2021

Estimate Repair Cost to Vehicle No :SMZ9824P

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
38 Side Trim -LH/RH	1,650.10	2 PC	3,300.20	X
39 Sill Plate	773.40	1 PC	773.40	X
40 Tail Lamp Assy -LH/RH	930.40	2 PC	1,860.80	X
41 Tail Lamp Protector -LH/RH	511.50	2 PC	1,023.00	X
42 Support Bracket -LH/RH	1,300.50	2 PC	2,601.00	X
43 Support Bracket Cap -LH/RH	899.50	2 PC	1,799.00	X
44 Trunk Cover End Trim	657.10	1 PC	657.10	X
45 Lift Gate Side Trim	1,565.00	2 PC	3,130.00	X
46 Lift Gate Lower Trim	1,610.50	1 PC	1,610.50	X
47 Lift Gate Upper Trim	1,600.40	1 PC	1,600.40	X
48 Trim Clips	8.00	7 PC	56.00	X
		(202)	43,384.30	43,384.30
Net Price				
49 Rear Number Plate	80.00	1 PC	80.00	35 S/N
50 Rear Number Plate Bracket	50.00	1 PC	50.00	X
			130.00	130.00
Labour				
51 Labour to dismantle lift gate & renew lift gate .	580.00	1 -	580.00	60
52 Labour to renew & refit bumper .	480.00	1 -	480.00	X
53 Labour to reconnect & renew tail lamp .	200.00	1 -	200.00	20
54 Labour to reconnect reverse buzzer & all sensors .	380.00	1 -	380.00	30
55 Labour to renew lift gate hydraulic lift gate .	580.00	1 -	580.00	X
56 Labour to knock ,weld & renew all accident affected area .	1,800.00	1 -	1,800.00	500
57 Labour to renew & dismantle lift gate windscreen .	480.00	1 -	480.00	120
58 To rust proofing on all affected area .	480.00	1 -	480.00	30
59 To spray & painting on affected area .	1,200.00	1 -	1,200.00	800
			6,180.00	6,180.00

P-544266
 202
 4434.13
 235
 1640
 6219.13
 202
 5017

HUP LIAN HUAT ENGINEERING WORKS

No.38 Defu Lane 9 , Singapore 539278
 TEL: 6282 3336 (3 Lines) FAX: 6289 3336 Email: mahlian@singnet.com.sg
 GST:52832105J RCB NO:201327339E

M/S : SOMPO INSURANCE SINGAPORE PTE LTD

50 Raffles Pl

#03-03 Singapore Land Tower,

Singapore 048623

TEL: 6461 6555

ATTN: Motor Claim Department

Your Ref No: CHUA CHENG LIANG

Claim Type: Third Party

Accident Date: 22/04/2024

TP Veh Reg No: EG9669R

Estimate No: ES1602141

Date: 22 Apr 2024

Policy No: DMPG23006775

Veh Reg No: SMZ9824P

Make/Model: MAZDA CX-5 2.0 AT
ELEGANCE 2WD I4

Chassis No: JM6KF2W7AM0676690

Engine No: PE31686659

Reg. Date: 27/05/2021

Estimate Repair Cost to Vehicle No :SMZ9824P

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
			Total	S\$ 49,694.30
			Add GST @ 9%	4,472.49
			Total Amount Payable	S\$ 54,166.79

TOTAL: SINGAPORE DOLLAR FIFTY FOUR THOUSAND ONE HUNDRED SIXTY SIX AND CENTS SEVENTY NINE ONLY

**For HUP LIAN HUAT ENGINEERING
WORKS**

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: