

祥輝汽車修理 SIANG HUI MOTOR WORKS

Blk 3006, Ubi Road 1 #01-338, Singapore 408700.

Tel: 67444605 Fax: 67440726

REG. No. 322208/00M

Date, 22-8-2024

Vehicle No SLN 7301U

1	IPC Rear bumper	\$ 628.00	cut/trim ✓
2	IPC Rear bumper lower	\$ 347.00	grind ✓
3	IPC Rear bumper reinforcement	\$ 313.00	one ✓
4	IPC Rear bumper side retainer	\$ 26.00	11 x
5	IPC Bumper reverse sensor	\$ 200.00	1 x
		\$ 1574.00	
Less 10%		\$ 157.40	
		\$ 1416.60	

Labour charges:-

1	To remove, ^{ref, x} replace Sensor and check wiring	\$ 60.00	30
2	To remove, replace bumper & panel beating	\$ 480.00	360
3	To spray painting	\$ 480.00	400
		\$ 2436.60	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Allowed
in
means
27/8/24
1/5 \$ 1600
3 days