



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24080368/Uqp3
(BUDGET DIRECT INSURANCE)	Date:	04/09/2024
190 CLEMENCEAU AVENUE #03-01	Code:	AGI
SINGAPORE SHOPPING CENTRE SINGAPORE 239924		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKK 1298M	Veh. Inspected	SJJ 3935L
Policy No.	-	Coverage	0
Claim No.	C10031270/KC	Excess	\$0.00
Assign From	KIAN CHUAN	Assign Date	22/08/2024

2. Vehicle Details

Make & Model	HONDA ACCORD 2.0 VTIS 5AT	C.C	1997
Engine No.	R20Z21600175	Year of Reg.	30/05/2017
Chassis No.	MRHCR1630GP000138	Colour	WHITE
Odometer	97536 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	235/45ZR18	PIRELLI	6
L/H Front Tyre	235/45ZR18	PIRELLI	6
R/H Rear Tyre	235/45ZR18	PIRELLI	6
L/H Rear Tyre	235/45ZR18	PIRELLI	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/08/2024	Inspection Date	26/08/2024
Survey held at	CARSMITH PTE LTD - 8 KAKI BUKIT AVE 4 #04-35 SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days