



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS SOMPO INSURANCE SINGAPORE PL	Ref:	CS/SMO24080369/Uvp3
50 RAFFLES PLACE #03-03	Date:	04/09/2024
SINGAPORE LAND TOWER SINGAPORE 048623	Code:	SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBS 9607S	Veh. Inspected	SLF 8348X
Policy No.	D23MTMC01003790	Coverage	0
Claim No.	CMTD2402731/JYC	Excess	\$0.00
Assign From	JIA YI	Assign Date	22/08/2024

2. Vehicle Details

Make & Model	TOYOTA PRIUS HYBRID (A)	C.C	1798
Engine No.	2ZRR928118	Year of Reg.	13/09/2016
Chassis No.	JTDKB3FUX03531364	Colour	WHITE
Odometer	236070 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	185/65R15	GRENLANDER	6
L/H Front Tyre	185/65R15	GRENLANDER	6
R/H Rear Tyre	185/65R15	FALKEN	6
L/H Rear Tyre	185/65R15	FALKEN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/08/2024	Inspection Date	26/08/2024
Survey held at	LLM AUTO LEASING PTE LTD - 1 KAKI BUKIT AVENUE 6, BLK C, #01-56, SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days