

LLM AUTO

LLM Auto Leasing Pte Ltd
c/o 1 Kaki Bukit Ave 6, Block C, #01-56
Singapore 417883

TEL : 96155115

EMAIL : llmautoleasing@gmail.com

not Authorized
an
26/8/24
2/s # 3000/
3 days.

VEHICLE No: SLF 8348X

1PC	REAR BUMPER	cut/Torn	\$721.30 ✓
1PC	REAR BUMPER DIFFUSER LOWER	ground	\$861.80 ✓
1PC	REAR SIDE BUMPER LOWER LH	Torn	\$290.50 ✓
1PC	REAR BUMPER SIDE RETAINER LH	Bent (one	\$68.80 ✓
1PC	REAR BUMPER BEAM	na	\$422.10 X
1PC	REAR BUMPER LAMP LH LOWER	one	\$752.80 ✓
1SET	REAR BUMPER CLIPS	na	\$50.00 ✓
1PC	REAR END PANEL	R	\$715.20 X
1PC	REAR SIGNAL LAMP N/S	one	\$677.80 ✓
1PC	REAR FENDER LH	R	\$1,299.20 X
			\$5,859.50
		LESS 25%	\$4,394.63

TO CHECK WIRING	\$50.00 20
TO DISMANTLE & REFIX REAR REVERSE SENSOR	\$50.00 30
TO SPRAY RUST PROOFING	11 \$80.00 X
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$80.00 60
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$880.00 480
TO PUTTY & SPRAY PAINTING	\$1,000.00 600
TOTAL	\$6,534.63

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 3423
252
2867.25
1190
3757.25
202
3005.