

Kenneth (LKK)
11/6/24

Not Attached
Purvey B4 pain



Estimation

3 days
8 4164.40

Date 7/6/2024
Vehicle SNJ 1932K
Make/Model MERCEDES BENZ E200
Chassis No. W1K2130802B044282

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	BONNET	1	\$ 2,846.20	\$ 2,846.20 X
2	FRON FENDER LH	1	\$ 1,466.50	\$ 1,466.50 X
3	FRONT DOOR LH	1	\$ 1,988.20	\$ 1,988.20 X
4	FRONT DOOR HINGE LH	2	\$ 145.00	\$ 290.00 X
5	FRONT VIEW MIRROR ASSEMBLY LH 3516	1	\$ 4,163.00	\$ 4,163.00 ✓
				\$ 10,753.90
			Less 10%	\$ 1,075.39
			Total	\$ 9,678.51

	S/Nett Items			
1	REAR FENDER CLIPS	1	\$ 80.00	\$ 80.00 X
2	REAR FENDER COWLING CLIPS	1	\$ 80.00	\$ 80.00 X
3	REAR FENDER INNER GARNISH CLIPS LH	1	\$ 80.00	\$ 80.00 X
4	REAR DOOR INNER TRIM CLIPS LH	1	\$ 80.00	\$ 80.00 X
			Total	\$ 320.00

	LABOUR			
1	SPRAY PAINT ON AFFECTED AREAS	1	\$ 1,400.00	\$ 1,400.00 800
2	PANEL BEATING ON AFFECTED AREAS	1	\$ 1,200.00	\$ 1,200.00 200
3	TO PERFORM RUST PROOFING	1	\$ 180.00	\$ 180.00 X
4	TO TRANSFER FRONT DOOR MECHANISM	1	\$ 80.00	\$ 80.00 X
			Total	\$ 2,860.00

Parts Replacement Amount	\$ 9,998.51
Total Amount For Labour	\$ 2,860.00
Total Amount	\$ 12,858.51

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

AP AUTOMOTIVE SERVICES PTE LTD

56 Loyang Way #04-04 Loyang Enterprise Building S508755 | UEN : 202022890H

Acknowledged by Repairer

Signature:

Date: