

Performance Motors

BMW Dealer



Final Report

Estimate No. : b1 70884
Date Estimated : 15/08/2024
Prepared By : Chua Kee Sin

Page No. :

- ESTIMATE REPAIR FOR -
Senku Production Engineering Pte Lt
21 Bukit Batok Crescent
#02-79 Wcega Tower

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 658065

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDQ2626U	WBA7T02030BS88889	20/07/2020	730Li Sedan	51221

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper panel include carrying out other necessary repairs caused by the accident	850.00		850.00
To spray paint rear bumper	1,038.00		1,038.00
To check electrical wiring system and lightings at the rear section for proper function	177.00		177.00
To remove PDC assembly, replace damaged parts include reconnecting to bumper and conducting checks for proper function	177.00		177.00
Sundries	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER PANEL PRIMED (PDC/PMA)	1,865.15	1.00	0.00	1,865.15

SUPPLEMENTARY ITEMS

Total Labour :	2,322.00
Total Parts :	1,865.15
Total Labour & Parts (before GST) :	4,187.15
Deduction for Excess :	
Total Repair Costs less Excess:	4,187.15
GST @9%:	376.84
Grand Total :	4,563.99

Performance Motors Limited.
Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W

A Sime Darby Motors Company

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



Due 22/8
Sum & Repair
9/9/24

GST REG. NO : M2 - 0020081 - X

ESTIMATE

15 AUG 2024

Estimate No. : b1 70884
Date Estimated : 15/08/2024
Prepared By : Chua Kee Sin

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Senku Production Engineering Pte Lt
21 Bukit Batok Crescent
#02-79 Wcega Tower

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 658065

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDQ2626U	WBA7T02030BS88889	20/07/2020	730Li Sedan	48019

DESCRIPTION

Replace rear bumper include remove attachment etc and carryout necessary repairing work on accident damage area

VALUE

~~850~~ 1,275.00

Painting rear bumper

~~1,038.00~~

To check electrical wiring system and lighting at the rear section for proper function.

~~177.00~~

Sundries.

~~80~~ 150.00

Total Labour 1: 2,640.00

DESCRIPTION

DESCRIPTION	QTY	PRIC	VALUE
Protection f <i>Xnn</i>	2	4.65	9.30
RH ABSORBER FUNNEL <i>Xnn</i>	1	55.50	55.50
REAR RH LATERAL MOUNT <i>Xnn</i>	1	177.55	177.55
RH EXHAUST TAILPIPE TRIM (6 ZYL CHR <i>Xnn</i>	1	396.70	396.70
REAR RH MOULDING ROCKER PANEL <i>Xnn</i>	1	52.50	52.50
LH PROTECTION FOIL <i>Xnn</i>	1	21.50	21.50
RH PROTECTION FOIL <i>Xnn</i>	1	21.50	21.50
REAR BUMPER PANEL PRIMED (PDC/PMA) <i>See</i>	1	1,865.15	1,865.15
SET MOUNTS PDC SENSOR REAR <i>Xnn</i>	1	75.55	75.55
REAR BUMPER COVER PRIMED <i>Xnn</i>	1	215.75	215.75
DECOUPLING RING <i>Xnn</i>	6	5.65	33.90
ULTRASONIC SENSOR SOPHISTO GREY <i>See Xnn</i>	1	404.25	404.25

Total Parts : 3,329.15

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 70884
Date Estimated : 15/08/2024
Prepared By : Chua Kee Sin

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDQ2626U	WBA7T02030BS88889	20/07/2020	730Li Sedan	48019

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement
Regn No. _____ Claim No. _____
Date&Time 09/09/24 Excess S\$ _____
Surveyor's Name Rasul Sign _____
Surveyor's Tel 9000068 Authorised Yes / No
Authorised Date _____ Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No
Surveyor's E-mail _____
No. of Working Days Recommend 3 days

Res by paint



Labour 1	:	2,640.00
Parts	:	3,329.15
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 9%	:	537.22
Grand Total	:	6,506.37