

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

GBJ1441C
TP1A1G

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

ATTN: Motor Claim Department

WS Ref: TP/AIG

Claim Type: Third Party

Accident Date: 19/08/2024

TP Veh Reg No: SMS2516L

FAX: 64153727

Not Authorised

61 Rpy & 2150h

Running After Police
4 days

Estimate No: ES2400737/WS

Date: 02 Sep 2024

Policy No: Z24VC05021758

Veh Reg No: GBJ1441C

Make/Model: KIA KIA K2500 6MT

Chassis No: KNCSJX76LK7327544

Engine No: D4CBJ699428

Reg. Date: 04/01/2019

Estimate Repair Cost to Vehicle No :GBJ1441C

Description	U/Price	Quantity	List Price	Amount
List Price			S\$	S\$
1 REAR STEP BAR	326.00	1 PC	326.00	—
2 REAR NUMBER PLATE LAMP	29.00	1 PC	29.00	—
3 TAILLAMP	196.00	2 PC	392.00	4196
4 TAILLAMP HOUSINGS	145.00	2 PC	290.00	4145
5 REAR EXHAUST PIPE	464.00	1 PC	464.00	—
6 REAR TAILGATE	595.00	1 PC	595.00	X
			2,096.00	
		Less 10%	209.60	1,886.40
Special Net				
7 REAR STEP CENTRE BEAM	120.00	1 PC	120.00	—
8 STICKER 70KM/HR	10.00	1 PC	10.00	—
9 STICKER 13 PAX	10.00	1 PC	10.00	—
10 REAR NUMBER PLATE	35.00	1 PC	35.00	—
11 REVERSE SENSOR	200.00	1 SET	200.00	—
			375.00	375.00
Labour				
12 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, REAR NO. PLATE LAMPS; TO KNOCKING & REPAIR TAILGATE, TAILGATE LOWER MEMBER & REALIGN THE SAME	700.00	1 LA	700.00	550
13 REMOVE & REFIX REAR EXHAUST & CHECK SYSTEM	60.00	1 LA	60.00	—
14 PUTTY & RESPRAY ON REAR BUMPER, TAILGATE, TAILGATE LOWER MEMBER & REAR BUMPER	600.00	1 LA	600.00	500
15 TO REWRITE ADVERTISEMENT	250.00	1 LA	250.00	180
			1,610.00	1,610.00

Parts # 1160
Less 10% 116
410.44
375
1290

2209

45 # 2150

Total S\$ 3,871.40

Add GST @ 9% 348.43

Total Amount Payable S\$ 4,219.83

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE