

CD/AIG 24080373/Kma3

ATTN: MR. Kenneth

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST: 201001158E RCB NO: 201001158E

GBJ1441C
TP1A1G

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000
 ATTN: Motor Claim Department
 WS Ref: TP/AIG
 Claim Type: Third Party
 Accident Date: 19/08/2024
 TP Veh Reg No: SMS2516L

FAX: 64153727

Not Notarised

11/10/2024 8 2150h

Penalty After 10am

4 days

Estimate No: ES2400737/WS
 Date: 02 Sep 2024
 Policy No: Z24VC05021758
 Veh Reg No: GBJ1441C
 Make/Model: KIA KIA K2500 6MT
 Chassis No: KNCSJX76LK7327544
 Engine No: D4CBJ699428
 Reg. Date: 04/01/2019

Estimate Repair Cost to Vehicle No :GBJ1441C

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR STEP BAR	326.00	1 PC	326.00	✓
2 REAR NUMBER PLATE LAMP	29.00	1 PC	29.00	✓
3 TAILLAMP	196.00	2 PC	392.00	✓ 196
4 TAILLAMP HOUSINGS	145.00	2 PC	290.00	✓ 145
5 REAR EXHAUST PIPE	464.00	1 PC	464.00	✓
6 REAR TAILGATE	595.00	1 PC	595.00	X
			2,096.00	
		Less 10%	209.60	1,886.40
Special Net				
7 REAR STEP CENTRE BEAM	120.00	1 PC	120.00	✓
8 STICKER 70KM/HR	10.00	1 PC	10.00	✓
9 STICKER 13 PAX	10.00	1 PC	10.00	✓
10 REAR NUMBER PLATE	35.00	1 PC	35.00	✓
11 REVERSE SENSOR	200.00	1 SET	200.00	✓
			375.00	375.00
Labour				
12 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, REAR NO. PLATE LAMPS; TO KNOCKING & REPAIR TAILGATE, TAILGATE LOWER MEMBER & REALIGN THE SAME	700.00	1 LA	700.00	550/
13 REMOVE & REFIX REAR EXHAUST & CHECK SYSTEM	60.00	1 LA	60.00	✓
14 PUTTY & RESPRAY ON REAR BUMPER, TAILGATE, TAILGATE LOWER MEMBER & REAR BUMPER	600.00	1 LA	600.00	500/
15 TO REWRITE ADVERTISEMENT	250.00	1 LA	250.00	180/
			1,610.00	1,610.00

Parts # 1160
 Less 10% 116
 1044
 375
 1290
 2209
 49 # 2150/

Total SS 3,871.40
 Add GST @ 9% 348.43
 Total Amount Payable SS 4,219.83

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE