



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2501969

INV Date 02/04/2025

Reference CD/LPC24080376/Tpa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMB 1644X
Insured Veh. GBF 4980P
Claim No. 23/24/24/VC05/028891
Policy No. Z23VC05021180
Accident Date 01/03/2024
Inspection Date 22/08/2024

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CD/LPC24080376/Tpa3q2(N)	
			Date: 02/04/2025	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBF 4980P	Veh. Inspected	SMB 1644X
	Policy No.	Z23VC05021180	Coverage (\$)	0.00
	Claim No.	23/24/24/VC05/028891	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	22/08/2024
2. Vehicle Particulars & Condition				
	Make & Model	MAN A22	c.c	10518
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	WMAA22ZZ3F7002646	Colour	MULTI COLOUR
	Odometer	692143 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	275/70 R22.5	BRIDGESTONE	8 mm
	L/H Front Tyre	275/70 R22.5	BRIDGESTONE	8 mm
	R/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	8/8 mm
	L/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	8/8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	01/03/2024	Inspection Date	22/08/2024
	Survey held at	STRIDES PREMIER AUTOMOTIVE SERVICES PL. 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 1644X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<u>REPLACEMENT OF PARTS</u>	TO REPAIR SEE LABOUR		
	COVER HEADLAMP ,FRT ,LH,FOR MAN A22 BUS		974.70	-
			974.70	-
	<u>LABOUR</u>			
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS .INCLUSIVE OF THE REPAIR OF COVER HEADLAMP ,FRT ,LH,FOR MAN A22 BUS .		795.00	530.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		708.00	538.00
			1,503.00	1,068.00
GRAND TOTAL			2,477.70	1,068.00
RECOMMENDED COST OF REPAIRS				1,068.00

Report Ref No. CD/LPC24080376/Tpa3q2(N)

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.


PHOTOGRAPHS FOR VEHICLE NO. : SMB 1644X




PHOTOGRAPHS FOR VEHICLE NO. : SMB 1644X



PHOTOGRAPHS FOR VEHICLE NO. : SMB 1644X



PHOTOGRAPHS FOR VEHICLE NO. : SMB 1644X





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 2 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SMB 1644X

