

Date: 19-8-2024
 Vehicle No: SJF371D
 Model: Tesla Model 3
 Chassis: LRW3F7EL6MC263490
 Reg. Year: 15.9.2021

Not Whaired
Minor B & Paim
4 days
@ 2428.28

Third Party Insurer: AIG
 Third Party Veh No: SGB4042J
 Date of Accident: 17/8/2024
 Estimator: Loong
 Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER	1	<i>Bul</i>	<i>Re</i> \$766.00 ✓
2	FRONT LH BUMPER RETAINER	1		<i>Di</i> \$1.86 ✓
3	FRONT LH BUMPER SIDE SUPPORT BRACKET	1		<i>CM</i> \$12.14 ✓
4	FRONT BUMPER ENERGY ABSORBER	1		<i>Sn</i> \$46.72 X
5	FRONT LH FOG LAMP	1		<i>Sn</i> \$271.02 X
6	FRONT PARKING SENSOR	2 ✓	\$163.55	<i>Re</i> \$327.10 ✓
7	FRONT PARKING SENSOR MOUNTING BRACKET	6	\$4.67	<i>Re</i> \$28.02 ✓
8	FRONT LH HEADLAMP	1		<i>Re</i> \$1,741.00 X
9	FRONT LH FENDER PANEL	1		<i>Re</i> \$448.59 ✓
10	FRONT LH FENDER LINER	1		<i>CM</i> \$116.82 ✓
11	FRONT LH KNUCKLE ARM	1		<i>Sn</i> \$420.56 X
12	FRONT LH KNUCKLE HUB + BEARING	1		<i>Re</i> \$149.53 X
13	FRONT LH LOWER ARM - STRAIGHT	1		<i>Sn</i> \$242.99 X
14	FRONT LH LOWER ARM - CURVED	1		<i>Sn</i> \$224.29 X
15	FRONT LH UPPER ARM	1		<i>Re</i> \$121.49 X
16	FRONT LH WHEEL RIM	1		<i>Re</i> REPAIR
			SUB TOTAL	\$4,918.13
			LESS 10%	-\$491.81
			PARTS TOTAL	\$4,426.32

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1		<i>Re</i> \$50.00 ✓
2	FRONT FENDER LINER CLIPS	1		<i>Re</i> \$50.00 ✓
3	FRONT BUMPER LOWER COVER CLIPS	1		<i>Re</i> \$50.00 X
			S/N TOTAL	\$150.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT LH ACCIDENT AREAS & ETC. \$700.00 *400*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRONT LH FENDER, ETC \$700.00 *440*

TO REMOVE AND REFIT FRONT UNDERCARRIAGE PARTS TO ENABLE REPAIR *Re* \$300.00 X

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554600
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1622 | Fax: (+65) 6481 1011



Date: 19-8-2024
Vehicle No: SJF371D
Model: Tesla Model 3
Chassis: LRW3F7EL6MC263490
Reg.Year: 15.9.2021

Third Party Insurer: AIG
Third Party Veh No: SGB4042J
Date of Accident: 17/8/2024
Estimator: Loong
Surveyor:

TO TUFF KOTE & UNDERSEAL MATERIALS.

301 \$100.00

TO REMOVE AND REFIT FRONT PARKING SENSORS

601 \$100.00

TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT

nn \$120.00 X

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$100.00 152

TO READJUST AND REALIGN HEADLAMP AIM

nn \$100.00 X

LABOUR TOTAL \$2,220.00

TOTAL \$6,796.32

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047

Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

