

XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Reg : 201838521G

DATE : 16.08.2024

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNG 1660K**
MODEL : **HONDA FIT**
CHASSIS : **GK31344167**
DATE OF REG : 11.04.2019
DATE OF ACCIDENT : 15.08.2024

Xiao Tony.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Del'd</i>	1	\$ 715.20	\$ 715.20
2	REAR BUMPER SIDE GARNISH <i>RT Amble'd</i>	2	\$ 75.80	\$ 151.60
3	REAR BUMPER CENTER GARNISH <i>Amble'd</i>	1	\$ 192.10	\$ 192.10
4	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 65.80	\$ 131.60
5	TAIL GATE <i>Dented</i>	1	\$ 905.80	\$ 905.80
6	TAIL GATE LAMP <i>new</i>	2	\$ 205.80	\$ 411.60
7	TAIL GATE OUTER MOULDING <i>new</i>	1	\$ 254.80	\$ 254.80
8	TAIL GATE LOGO <i>new</i>	1	\$ 80.90	\$ 80.90
9	TAIL GATE EMBLEM 'FIT' <i>new</i>	1	\$ 78.50	\$ 78.50
10	TAIL GATE DAMPER <i>new</i>	2	\$ 104.20	\$ 208.40
11	TAIL GATE INNER HOLDER <i>new</i>	1	\$ 49.80	\$ 49.80
12	TAIL GATE STOPPER	2	\$ 12.00	\$ 24.00
13	TAIL GATE INNER LOCK <i>Dented</i>	1	\$ 198.50	\$ 198.50
14	TAIL GATE LOCK CATCH <i>new</i>	1	\$ 25.00	\$ 25.00
15	TAIL GATE WEATHER STRIP <i>lit</i>	1	\$ 175.20	\$ 175.20
16	TAIL GATE INNER TRIM <i>Amble'd</i>	1	\$ 245.90	\$ 245.90
17	TAIL GATE HINGE <i>new</i>	2	\$ 65.80	\$ 131.60
18	TAIL GATE DETECTOR <i>Amble'd</i>	1	\$ 265.90	\$ 265.90
19	TAIL GATE BUZZER <i>new</i>	1	\$ 135.70	\$ 135.70
20	TAIL GATE WINDSCREEN MOULDING <i>new</i>	2	\$ 98.60	\$ 197.20
21	TAIL LAMP <i>RT Amble'd</i>	2	\$ 328.50	\$ 657.00
22	TAIL LAMP LOWER PANEL (OUTER) <i>new</i>	2	\$ 117.90	\$ 235.80
23	TAIL LAMP INNER PANEL (LOWER)	2	\$ 147.70	\$ 295.40
24	REAR FENDER INNER COWLING <i>new</i>	2	\$ 125.60	\$ 251.20
25	REAR FENDER INNER TRIM <i>RT Del'd</i>	2	\$ 305.20	\$ 610.40
26	REAR END PANEL <i>Dented</i>	1	\$ 408.50	\$ 408.50
27	REAR END PANEL TOP GARNISH <i>Del'd</i>	1	\$ 175.80	\$ 175.80
28	REAR FLOOR PANEL <i>new</i>	1	\$ 796.10	\$ 796.10
29	REAR FLOOR PANEL TOP BOARD <i>Del'd</i>	1	\$ 205.90	\$ 205.90

525

✓

✓

✓

✓

+

+

+

+

+

+

+

✓

✓

✓

+

+

+

✓

✓

+

+

+

328.50

✓

✓

+

✓

✓

TO : **AIG MOTOR CLAIMS DEPTS**
 VEHICLE NO : **SNG 1660K**
 MODEL : **HONDA FIT**
 CHASSIS : **GK31344167**
 DATE OF REG : **11.04.2019**
 DATE OF ACCIDENT : **15.08.2024**

30	REAR TOOLS COMPARTMENT SPONGE <i>hubd</i>	1	\$ 212.30	\$ 212.30
----	---	---	-----------	-----------

TOTAL PRICE \$ 8,427.70
 LESS 20% \$ 1,685.54
SUB TOTAL PRICE \$ 6,742.16

4571.90

3657.52 ✓

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE WITH CASING <i>new</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
3	REAR BUMPER CENTER GARNISH CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
4	TAIL GATE INNER TRIM CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
5	TAIL GATE WINDSCREEN SEALANT <i>2pac</i>	1	\$ 80.00	\$ 80.00
6	TAIL GATE WINDSCREEN INNER SEAL <i>new</i>	1	\$ 60.00	\$ 60.00
7	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
8	TAIL LAMP LOWER PANEL (OUTER) SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
9	REAR FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
10	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
11	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00
12	REAR FLOOR PANEL SEALANT <i>new</i>	1	\$ 250.00	\$ 250.00
13	REVERSE CAMERA <i>new</i>	1	\$ 450.00	\$ 450.00
14	REVERSE SENSOR (SET) <i>2nd</i>	1	\$ 250.00	\$ 250.00

TOTAL \$ 1,640.00

420

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,000.00	800
2	TO SPRAY PAINT AFFECTED AREA	\$ 2,000.00	800
3	TUFF COAT	\$ 200.00	60
4	WIRING CHECK ON TAILAMP	\$ 80.00	30
5	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNG 1660K**
 MODEL : **HONDA FIT**
 CHASSIS : **GK31344167**
 DATE OF REG : **11.04.2019**
 DATE OF ACCIDENT : **15.08.2024**

6	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY TO FACILITATE REPAIR	\$ 200.00	60
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 100.00	50
8	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 100.00	50
9	REMOVE AND VIDEO FOOATGE AND DISTANCE SETTING	\$ 80.00	50
12	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
13	TRANSFER TAILGATE MECHANISM	\$ 80.00	60
16	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 200.00	X

2080

TOTAL \$ 5,240.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,382.16
 TOTAL LABOUR COST : \$ 5,240.00
 TOTAL REPAIR COST : \$ 13,622.16

Admaly
L/S 16/08/24

08 Aug.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Supplementary: 51136.88
 total: 7294.40
 L/S: 5.8/K

(5.8/K)

REQUEST FOR SUPPLEMENTS PARTS/ LABOUR

Vehicle No	SNG 1660K	Date of Request	16.08.2024	
Vehicle Model	HONDA FIT	Number of Days to Extend (If any)		
S/N	Part Description	QTY	LIST PRICE	TOTAL PRICE
1	REAR FENDER RH <i>Buckled</i>	1	897.5	897.5 ✓
2	REAR SILENCER BOX <i>Dented</i>	1	523.6	523.6 ✓
TOTAL				1421.1

Adm Lj
[Signature]

1421.10
Supplementary : 1136.88