

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNG 1660K**
 MODEL : **HONDA FIT**
 CHASSIS : **GK31344167**
 DATE OF REG : **11.04.2019**
 DATE OF ACCIDENT : **15.08.2024**

30	REAR TOOLS COMPARTMENT SPONGE <i>hubhd</i>	1	\$ 212.30	\$ 212.30
TOTAL PRICE				\$ 8,427.70
LESS 20%				\$ 1,685.54
SUB TOTAL PRICE				\$ 6,742.16

457190
3657.52

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE WITH CASING <i>new</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
3	REAR BUMPER CENTER GARNISH CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
4	TAIL GATE INNER TRIM CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
5	TAIL GATE WINDSCEEN SEALANT <i>2 year</i>	1	\$ 80.00	\$ 80.00
6	TAIL GATE WINDSCEEN INNER SEAL	1	\$ 60.00	\$ 60.00
7	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
8	TAIL LAMP LOWER PANEL (OUTER) SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
9	REAR FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
10	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
11	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00
12	REAR FLOOR PANEL SEALANT <i>new</i>	1	\$ 250.00	\$ 250.00
13	REVERSE CAMERA <i>new</i>	1	\$ 450.00	\$ 450.00
14	REVERSE SENSOR (SET) <i>2nd</i>	1	\$ 250.00	\$ 250.00
TOTAL				\$ 1,640.00

420

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,000.00	<i>800</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 2,000.00	<i>800</i>
3	TUFF COAT	\$ 200.00	<i>60</i>
4	WIRING CHECK ON TAILLAMP	\$ 80.00	<i>30</i>
5	CONDUCT WATER LEAKAGE TEST	\$ 80.00	<i>X</i>

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNG 1660K**
 MODEL : **HONDA FIT**
 CHASSIS : **GK31344167**
 DATE OF REG : **11.04.2019**
 DATE OF ACCIDENT : **15.08.2024**

6	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY TO FACILITATE REPAIR	\$ 200.00	60
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 100.00	50
8	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 100.00	50
9	REMOVE AND VIDEO FOOATGE AND DISTANCE SETTING	\$ 80.00	50
12	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
13	TRANSFER TAILGATE MECHANISM	\$ 80.00	60
16	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 200.00	X

2080

TOTAL \$ 5,240.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,382.16
 TOTAL LABOUR COST : \$ 5,240.00
 TOTAL REPAIR COST : \$ 13,622.16

Admaly
 h/s 16/08/24

08 hrs.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Supplementary: \$ 1136.88
 total: 7284.40
 h/s: S.B.K

(S.B.K)

REQUEST FOR SUPPLEMENTS PARTS/ LABOUR

Vehicle No	SNG 1660K	Date of Request	16.08.2024
Vehicle Model	HONDA FIT	Number of Days to Extend (If any)	

S/N	Part Description	QTY	LIST PRICE	TOTAL PRICE
1	REAR FENDER RH <i>Buckled</i>	1	897.5	897.5 ✓
2	REAR SILENCER BOX <i>Dented</i>	1	523.6	523.6 ✓
TOTAL				1421.1

Adnan Lij
[Signature]

1421.10
Supplementary: 1136.88