

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

LIBERTY INSURANCE PRIVATE LIMITED
51 CLUB STREET #03-00 LIBERTY HOUSE
SINGAPORE 069428

Attention : Motor Claim Department

Contact : 62218611 Fax No. : 62241047

*Not Authored
Mr
Moras
23/8/24
1/5 #4300/
Tanjung Ht. Ateng
6 days*

Estimate : ES709593

Date : 21/08/2024
Vehicle Num. : SMD 3695A
Make/Model : HYUNDAI ACCENT
Chassis/Eng# :
Accident Date : 20/08/2024
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1PC	BOOT LID <i>DD/guc</i>		1,468.00 ✓
2.	1PC	BOOT LID LOCK <i>SVC</i>		197.00 ✗
3.	1PC	BOOT LID WEATHERSTRIP <i>7m/</i>		185.00 ✓
4.	1PC	BOOT LID LOGO <i>neu</i>		57.00 ✓
5.	1PC	BOOT LID ACCENT EMBLEM <i>neu</i>		52.00 ✓
6.	1PC	REAR BUMPER <i>DD</i>	485.30	688.00 ✓
7.	2PCS	REAR BUMPER SIDE RETAINER <i>neu</i>	48.00	96.00 ✗
8.	1PC	REAR BUMPER REINFORCEMENT <i>CNe</i>	376.20	492.00 ✓
9.	2PCS	REAR BUMPER REINFORCEMENT BRACKET <i>NF</i>	68.00	136.00 ✗
10.	4PCS	REAR BUMPER REINFORCEMENT PLASTIC BRACKET <i>7m</i>	20.00	80.00 ✓
11.	2PCS	REAR BUMPER REFLECTOR <i>MS neu olscra</i>	99.00	198.00 <i>IPC</i>
12.	4PCS	REVERSE SENSOR <i>SVC</i>	256.00	1,024.00 ✗
13.	1PC	REVERSE SENSOR WIRE HARNESS <i>neu</i>		322.00 ✗
14.	4PCS	REVERSE SENSOR BRACKET <i>neu</i>	32.00	128.00 ✓
15.	4PCS	REVERSE SENSOR ORING <i>neu</i>	15.00	60.00 ✗
16.	1PC	REAR END PANEL <i>3.0/5.00</i>	592.00	658.00 ✓
17.	1PC	REAR END PANEL GARNISH <i>7m/</i>		176.00 ✓
18.	1PC	SPARE TYRE BOARD <i>wopuh/CNe</i>	366.00	497.00 ✓
List TotalS\$:				6,514.00
20.00% Discount S\$:				1,302.80
<i>IPC</i> <i>tail lamp n/s</i> <i>380-50 CNe</i>				5,211.20

CONTINUE / ...

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

LIBERTY INSURANCE PRIVATE LIMITED
51 CLUB STREET #03-00 LIBERTY HOUSE
SINGAPORE 069428

Attention : Motor Claim Department
Contact : 62218611 Fax No. : 62241047

Estimate : ES709593

Date : 21/08/2024
Vehicle Num. : SMD 3695A
Make/Model : HYUNDAI ACCENT
Chassis/Eng# :
Accident Date : 20/08/2024
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1PC	SPECIAL NETT ITEMS :		
2.	1SET	BOOT LID SEALANT 11	80.00	X
3.	1SET	REAR BUMPER CLIP 11	50.00	30 s/n
3.	1SET	REAR BUMPER RIVET 11	50.00	X
4.	1SET	REAR FENDER INNER TRIM CLIP 11	50.00	X
Special Nett Total S\$:			230.00	
LABOUR :				
TO CHECK LIGHT AND WIRING			50.00	20
TRANSFER BOOT LID PARTS			100.00	50
ANTI-RUST			120.00	50
TO APPLY BODY SEALANT ON BODY JOINTS			120.00	X
INSTALL REVERSE SENSOR			80.00	30
INSTALL REVERSE CAMERA			120.00	X
TO REMOVE/REFIT GARNISH AND TRIMS TO FACILITATE REPAIRS			150.00	60
LABOUR/PANEL BEATING			900.00	800
SPRAY PAINTING			1,000.00	800
Labour Total S\$:			2,640.00	

E. & O.E.	Total S\$:	8,081.20
-----------	-------------	----------


for FALCON AIR AUTO SERVICES PTE LTD
TAMPINES BRANCH

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2-4445
202
3856
30
1810
5396
212
4316