

JEC AUTO SERVICE PTE LTD

1 KAKI BUKIT AVENUE 6, #02-11 AUTOBAY@KAKI BUKIT
SINGAPORE 417883
TEL: 92327457

TO	NTUC	DATE	22/8/2024
VEHICLE NO	: GBL7171G(2020)		Hui Rong
VEHICLE MODEL	: TOYOTA HIACE DX		
CHASSIS NO	: GDH2012014663		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Distahd</i>	1	\$ 673.10	\$ 673.10
2	REAR BUMPER SIDE HOLDER <i>new</i>	2	\$ 55.20	\$ 110.40
3	REAR BUMPER STEP PANEL <i>Dented</i>	1	\$ 281.70	\$ 281.70
4	REAR BUMPER LOWER BRACKET <i>Best</i>	4	\$ 18.50	\$ 74.00
5	REAR END PANEL OUTER <i>Dented</i>	1	\$ 768.90	\$ 768.90
6	REAR END PANEL INNER <i>Dented</i>	1	\$ 885.90	\$ 885.90
7	REAR END PANEL EXTENSION <i>LH Dented</i>	2	\$ 496.40	\$ 992.80
8	REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 185.60	\$ 185.60
9	TAILLAMP <i>crushed</i>	1	\$ 395.40	\$ 395.40
10	TAILLAMP PANEL OUTER <i>2 repair</i>	1	\$ 594.90	\$ 594.90
11	TAILLAMP PANEL INNER <i>Repair</i>	1	\$ 490.60	\$ 490.60
12	TAILLAMP LOWER APRON <i>Repair</i>	1	\$ 167.20	\$ 167.20
13	TAILLAMP LOWER APRON RETAINER <i>new</i>	1	\$ 65.10	\$ 65.10
14	TAILGATE <i>Dented</i>	1	\$ 2,054.30	\$ 2,054.30
15	TAILGATE LOCK <i>Repair</i>	1	\$ 475.60	\$ 475.60
16	TAILGATE LOCK COVER <i>Dented</i>	1	\$ 58.10	\$ 58.10
17	TAILGATE ACTUATOR LOCK <i>new</i>	1	\$ 381.50	\$ 381.50
18	TAILGATE WEATHERSTRIPE <i>for</i>	1	\$ 395.20	\$ 395.20
19	TAILGATE OUTER GARNISH <i>new</i>	1	\$ 266.50	\$ 266.50
20	TAILGATE INNER TRIM BOARD <i>new</i>	1	\$ 289.40	\$ 289.40
21	TAILGATE DAMPER <i>new</i>	2	\$ 275.20	\$ 550.40
22	TOYOTA LOGO <i>new</i>	1	\$ 63.40	\$ 63.40
23	REAR BODY PANEL AIR VENT <i>new</i>	1	\$ 86.30	\$ 86.30
24	REAR EXHAUST PIPE <i>2 new</i>	1	\$ 873.20	\$ 873.20
25	REAR EXHAUST PIPE MOUNTING <i>new</i>	1	\$ 35.80	\$ 35.80
26	SPARE TYRE CARRIAGE <i>Best</i>	1	\$ 345.20	\$ 345.20

TOTAL PRICE: \$ 11,560.50
LESS 25% \$ 2,890.12
SUB TOTAL PRICE: \$ 8,670.38

6967.20

\$ 225.40

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER CLIPS	1 SET	\$ 30.00	\$ 30.00
2	REAR END PANEL SEALANT	1 SET	\$ 60.00	\$ 60.00
3	REAR END PANEL EXTENSION SEALANT	1	\$ 60.00	\$ 60.00
4	REAR END PANEL TOP GARNISH RIVETS	1 SET	\$ 20.00	\$ 20.00
5	TAILLAMP LOWER APRON CLIPS	1 SET	\$ 20.00	\$ 20.00
6	TAILLAMP PANEL SEALANT	1	\$ 60.00	\$ 60.00
7	TAILGATE OUTER GARNISH CLIPS	1 SET	\$ 20.00	\$ 20.00
8	TAILGATE INNER TRIM COVER CLIPS	1 SET	\$ 30.00	\$ 30.00
9	TAILGATE GLASS SEALANT	1 SET	\$ 60.00	\$ 60.00
10	70KM/H STICKER	1	\$ 15.00	\$ 15.00
11	1200KG STICKER	1	\$ 25.00	\$ 25.00
12	FLOOR PANEL TOP BOARD	1	\$ 850.00	\$ 850.00
TOTAL :				\$ 1,250.00

Reverse Sensor
Damaged

280 200.

420

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,400.00	800	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	600	
3	WIRING CHECK	\$ 50.00	30	
4	TO APPLY TUFF COAT	\$ 150.00	60	
5	TO REMOVE UPHOLSTRY	\$ 150.00	20	
6	TO REMOVE TAILGATE GLASS	\$ 180.00	120	
7	TO TRANSFER TAILGATE FITTINGS	\$ 150.00	60	
8	TO REMOVE REAR EXHAUST PIPE	\$ 150.00	X.	
TOTAL:		\$ 3,430.00		

ESTIMATE REPORT

TOTAL PARTS COST: \$ 9,920.38

TOTAL LABOUR COST: \$ 3,430.00

TOTAL REPAIR COST: \$ 13,350.38

1700

total: 67345.40

L/S: 5.8K

06 Days

5.8K

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: