



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)	Ref:	CS/SPF24080382/Eqp3m4
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE)	Date:	10/09/2024
POLICE LOGISTICS BASE (PLB)	Code:	SPF
1 HEMMANT ROAD SINGAPORE 438675		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 1768J	Veh. Inspected	SKZ 4387R
Policy No.	-	Coverage	0
Claim No.	ACS/105/009/2024/029 (LK)	Excess	\$0.00
Assign From	LAI PENG CHONG	Assign Date	20/08/2024

2. Vehicle Details

Make & Model	TOYOTA VELLFIRE	C.C	2493
Engine No.	2ARH592748	Year of Reg.	22/01/2016
Chassis No.	AGH300028808	Colour	BLACK
Odometer	255857 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	235/50ZR18	KAPSEN	5
L/H Front Tyre	235/50ZR18	KAPSEN	5
R/H Rear Tyre	235/50ZR18	KAPSEN	5
L/H Rear Tyre	235/50ZR18	KAPSEN	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/06/2024	Inspection Date	21/08/2024
Survey held at	2ND AUTO PTE LTD 15 KAKI BUKIT ROAD 4, #01-53, BARTLEY BIZ CENTRE, SINGAPORE 417808		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days