



Not Arthur
meray
23/8/24
d/s \$ 1550
Lump Sum Part by Part
3 Lys.

ASSESSMENT FOR REPAIR : FBU8270A
YAMAHA AEROX
COE EXPIRY : 10.12.2028

Lump Sum Part by Part

Qty	Description	Repairer's Estimate	1st Survey	Repair Survey	Final Survey
1	HANDLE BAR	110.00	BNP ✓		
1	BAR END MIRROR (L&R SET)	68.67	C47 ✓		
1	RH - BRAKE PUMP	353.16	C47 ✓		
1	RH - LEVER	19.62	C47 ✓		
1	RH - FOOT MAT STAY	35.37	R7X		
1	RH - FOOT MAT COVER	35.37	C47 ✓		
1	RH - PILLION FOOTPEG	39.24	C47 ✓		
1	RH - PILLION FOOTREST BRACKET	98.10	R7X		
1	EXHAUST PROTECTOR	110.16	M.S ✓		
1	HEADLAMP STAY	49.05	R7X		
1	REAR SUSPENSION	667.08	SC R7X		
1	AIR BOX COVER (BIG)	29.43	C47 ✓		
1	AIR BOX COVER (SMALL)	19.62	C47 ✓		
1	AIR BOX INNER	39.24	R7X		
1	CVT COVER	106.56	C47 ✓		
		1,780.67			

102

Special Nett Items

STEERING CONE & BEARING	130.00	R7X		
FRONT FORK ALIGNMENT	230.00	SO		
WHEEL ALIGNMENT	130.00	R7X		
FRAME ALIGNMENT	210.00	R7X		
REAR TOP BOX (KAPPA)	504.00	C47 300 S/N		
FULL SET COVER SET	549.36	C47 ✓		

102 -

1,753.36

Total Parts 3,534.03

Labour Charges

1 Workmanship to renew damage parts & areas	400.00	300
\$100 per days X 4 days	400.00	

Total Parts & Labours Concluded 3,934.03

R-1441-19
102
1297.08
300
350
1947.08
202
1557

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature: _____
Date: _____

SANFU MOTOR PTE LTD
Company Reg No.: 200612487G
1 Kaki Bukit Ave 6, #02-43, AutoBay@Kaki Bukit, Singapore 417883
Direct Line: 9061 3299 Tel: (65) 6744 7753 Fax: (65) 6744 6010
Email: sanfumotor0243@gmail.com