



Final Report

Estimate No. : **b1 70945**
Date Estimated : **21/08/2024**
Prepared By : **Inthiran A/L Thurasamy**

Page No. :

- ESTIMATE REPAIR FOR -

Christopher Ng Chee Mun
4 Queen Astrid Garden

SINGAPORE
Singapore 266860

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SDA868K	WBY2Z22040VX65446	26/06/2015	I8	95401

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front bumper panel, front seal engine bonnet include carrying out other necessary repairs caused by the accident	1,275.00		1,275.00
To spray paint front bumper (2 colours)	1,557.00		1,557.00
To check electrical wiring system of the front section for proper function	177.00		177.00
To remove old PDC assembly, replace damaged parts and reconnect to bumper include conducting checks for proper function	177.00		177.00
Sundries	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT SEAL ENGINE BONNET	86.25	1.00	0.00	86.25
FRT BUMPER PANEL PRIMED ECE	1,952.40	1.00	0.00	1,952.40

SUPPLEMENTARY ITEMS

Total Labour :	3,266.00
Total Parts :	2,038.65
Total Labour & Parts (before GST) :	5,304.65
Deduction for Excess :	
Total Repair Costs less Excess:	5,304.65
GST @9%:	477.42
Grand Total :	5,782.07

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W

