

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI24090021/EVP3M4
Date: 09/09/2024

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MAA00605
Claimant Vehicle No :	SHB2988G	Insured Vehicle No :	SNQ4701D
Date of Loss:	31/08/2024	Nature of Claim:	TP
		Claim No:	M2405004

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB2988G	Engine No:	G4LEKU391104
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Chassis No:	KMHC851CVLU184586
Reg. Date:	30/10/2020 (Man. Year: 2019)	Odometer:	603247 km
Colour:	Yellow		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,360.56	851.12	509.44	37.44
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	855.00	785.00	70.00	8.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,227.56	1,648.12	579.44	26.01
Approved Total (Overridden) (S\$)		1,300.00		
(S\$)	2,227.56	1,300.00	927.56	41.64
+ GST 9.00/9.00% (S\$)	200.48	117.00	83.48	41.64
Nett Amount (S\$)	2,428.04	1,417.00	1,011.04	41.64

INSPECTION

Date of Assignment:	02/09/2024	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	02/09/2024	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 09 Sep 2024)
Parts: 143	HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHB2988G)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Broken	459.40 FL	*459.40 FL
2	1		*REAR BUMPER BEAM	Not Necessary	394.80 FL	*- FL
3	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
4	1		*REAR BUMPER CENTRE MOULDING	Deformed	451.25 FL	*451.25 FL
5	1		*REAR BUMPER MAT	Necessary	50.00 F	*50.00 F
6	1		*REAR NUMBER PLATE	Broken	55.00 F	*55.00 F
7	1		*REAR FOG LAMP	Not Necessary	201.50 FL	*- FL
8	1		*ANTENNA SMARTKEY	Not Necessary	40.50 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	1,674.45	1,037.65
- List Item Discount on L Items 20.00/20.00% (\$)	313.89	186.53
Total Parts (\$)	1,360.56	851.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	12.00	12.00
			Sub Total (\$)	12.00
				12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	400.00	380.00
2	SPRAYPAINT CHARGES	New	300.00	280.00
3	REMOVE/REFIX REVERSE SENSOR	New	50.00	20.00
4	TOWING FEE	New	105.00	105.00
			Gross Labour Cost (\$)	855.00
				785.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >