

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Crystabelle Tan

Date: 26 Aug 2024

Preliminary Advice

Vehicle No	: SMM3167K	Accident Date	: 08/08/2024
Make	: KIA CERATO	Policy No.	: MCF24B00000800
Assignment Date	: 22/08/2024	Excess	: S\$1,500.00
Date of Inspection	: 23/08/2024	Est. Duration of Repair	: 7
Inspection At	: DIPLOMAT PARTS PTE LTD (HQ) 209 PANDAN GARDENS SINGAPORE 609339		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,913.70
Revised Amount	:S\$	7,783.24
Check Items (Estimated)	:S\$	1,890.46
Total	:S\$	9,673.70
 Lump Sum Repair	 :S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	68,000.00
COE / PARF Rebate	:S\$	22,759.00
Salvage Value	:S\$	
Margin for Repair	:S\$	45,241.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.