

Reference

Part Source: MRM-SG

Parts: 143

Labour: Repairer's

Print Code: **Diplomat Parts Pte Ltd/SMM3167K/22/08/2024 10:22**

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Version: 1.0 (Last Synchronised: 22 Aug 2024)
 KIA CERATO 1.6 (A) (Catalogue:Merimen Singapore 1.0)
 (Price-denominated Standard List)

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*PANEL ASSY-HOOD <i>bt</i>	0.00	0.00	1442 1,311.00 F
2	1		*PAD-HOOD INSULATING <i>de</i>	0.00	0.00	122.10 *111.00 F
3	13		*CLIP-HOOD INSULATING PAD <i>re</i>	0.00	0.00	17.16 *15.60 F
4	1		*LATCH ASSY-HOOD <i>? xsvc</i>	0.00	0.00	*61.80 F
5	1		*COVER-FR BUMPER <i>Tom</i>	0.00	0.00	438.90 *399.00 F
6	1		*GRILLE ASSY-RADIATOR <i>cm</i>	0.00	0.00	226.38 *205.80 F
7	1		*GARNISH-RADIATOR GRILLE <i>cm</i>	0.00	0.00	33 *30.00 F
8	1		*GRILLE-FRONT BUMPER <i>cm</i>	0.00	0.00	172.92 *157.20 F
9	1		*MOULDING-FRONT BUMPER,RH <i>? xsvc</i>	0.00	0.00	*21.60 F
10	1		*ABSORBER-FRONT BUMPER ENERGY <i>cm</i>	0.00	0.00	55.44 *50.40 F
11	1		*ORNAMENT-KIA NO.115 <i>re</i>	0.00	0.00	30.35 *27.60 F
12	1		*STIFFNER-FR BPR LWR <i>? xsvc</i>	0.00	0.00	*68.40 F
13	1		*BEAM COMPLETE-FR BUMPER <i>bt</i>	0.00	0.00	328.80 *298.20 F
14	1		*CARRIER ASSY-FRONT END MODULE <i>? xsvc</i>	0.00	0.00	*405.00 F
15	1		*PANEL-FENDER,RH <i>bt</i>	0.00	0.00	430.32 *391.20 F
16	1		*LAMP ASSY-HEAD,LH <i>cm</i>	0.00	0.00	823.02 *748.20 F
17	1		*LAMP ASSY-HEAD,RH <i>cm</i>	0.00	0.00	823.02 *748.20 F
18	1		*CONDENSER ASSY-COOLER <i>bt</i>	0.00	0.00	445.50 *405.00 F
19	1		*RADIATOR ASSY <i>? xsvc</i>	0.00	0.00	*448.80 F
20	1		*BLOWER ASSY <i>? xsvc</i>	0.00	0.00	*425.40 F
21	1		*RESERVOIR & PUMP ASSY-WASHER <i>? xsvc</i>	0.00	0.00	*87.60 F

F=Franchise part.

Sub Total (S\$)	6,417.00
+ Margin on L,N Items 10.00% (S\$)	641.70
Total Parts (S\$)	7,058.70

Diplomat Parts Pte Ltd/SMM3167K/22/08/2024 10:22. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Particulars	Amount
1	ANTI-RUST PROOFING BONNET, FRT LHS FENDER, FRT RHS FENDER, FRT RHS DOOR	100.00
2	APPLY BODY SEALANT ON AFFECTED AREA	80 100.00
3	SUPPLY FRONT LICENSE PLATE WITH CASING ✓	35.00
Sub Total (S\$)		235.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	FRT BUMPER	New	200.00 ✓
2	BONNET	New	200.00 ✓
3	FRT LHS FENDER	New 1000	200.00 ✓
4	FRT RHS FENDER	New	200.00 ✓
5	FRT RHS DOOR	New	200.00 ✓
Labour Items			
6	FRT BUMPER ✓	New	220.00 ✓
7	BONNET ✓	New	220.00 ✓
8	FRT RHS FENDER ✓	New	220.00 ✓
9	FRT SUPPORT PANEL 9. XAN	New 880	220.00 ✓
10	FRT LHS FENDER repair ✓	Repair	110 220.00 ✓
11	FRT RHS DOOR repair ✓	Repair	110 220.00 ✓
12	TO CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	50.00 ✓
13	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	X 250.00 XAN
Gross Labour Cost (S\$)			2,620.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Diplomat Parts Pte Ltd/SMM3167K/22/08/2024 10:22. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

SURVEYOR NAME: Rasmy - Hy 9001068
 SURVEYOR SIGNATURE: [Signature]
 DATE: 23/08/24
 REMARKS: 7 days / repair
Resin 6k put
EXCESS: 1500



Diplomat Parts Pte. Ltd.

Company Reg No: 196402004
GST Reg No: M8-802211-0

PRO-FORMA INVOICE

THIS IS NOT AN OFFICIAL TAX INVOICE

Invoice Name & Address

Owner Name & Vehicle Info

Cycle & Carriage Leasing Pte Ltd

239 ALEXANDRA ROAD

Singapore 159930
159930

Contact No Mobile: 91185739

Reg No/Reg Date SMM3167K / 26/06/2019

Date In/Mileage 02/09/2024/ 132914

Chassis No KNAF3416MK5045442

Engine No G4FGKH738449

Make/Model KIA/CERATO 1.6 A EX 6333

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00061	Cash	12/10/2024/ 12:39	BLL	1210/ Lim Teng Keat	33394

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X KS 86370 M6 000 GARNISH-RADIATOR GRILLE <i>cm</i>	1.00	33.00	00.00	33.00
X KS 86530 M6 000 GRILLE-FRONT BUMPER <i>cm</i>	1.00	172.92	00.00	172.92
X KS 66920 M6 000 HINGE ASSY-HOOD,RH <i>bt</i>	1.00	28.38	00.00	28.38
X KS 66910 M6 000 HINGE ASSY-HOOD,LH <i>bt</i>	1.00	28.38	00.00	28.38
X KS 29134 M6 000 GUARD-AIR,RH <i>cm</i>	1.00	18.48	00.00	18.48
X KS 96611 M6 000 HORN ASSY-LOW PITCH <i>cm</i>	1.00	48.84	00.00	48.84
X KS 64101 M6 001 CARRIER ASSY-FRONT END MODULE <i>cm</i>	1.00	445.50	00.00	445.50
X KS 86150 M6 900 COVER ASSY-COWL TOP <i>cm</i>	1.00	163.02	00.00	163.02
X KS 14206 08 250B CLIP <i>nu</i>	10.00	0.66	00.00	6.60
X KS 86155 2H 100 RETAINER-COWL TOP COVER MTG <i>nu</i>	10.00	1.32	00.00	13.20
E PNT80000 ADDITIONAL JOB - REPLACE FRT SUPPORT PANEL				220.00 ✓
A 25000001 ADDITIONAL JOB - VACUUM & TOP UP A/CON GAS				220.00 ✓

Pro Forma

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	958.32			
Labour	440.00			
Standard Menu	0.00	9% GST on	1398.32	1,398.32
Specialist Job	0.00			125.85
Others(Lub,etc)	0.00			
Sundry	0.00			
Total(w/o GST)	1,398.32			
			Total Payable	1,524.17

This is not an official tax invoice. This is a computer generated document, no signature is required.

DPS Auto Services

209 Pandan Gardens, Singapore 609339 Tel: (65) 64792792