

GREEN FOREST AUTOMOBILE PTE LTD

8 KAKI BUKIT AVE 4 #05-25 PREMIER @ KB SINGAPORE 415875

TP Great America
Hui Roy
22nd AUGUST 2024

GREEN FOREST LANDSCAPE PTE LTD

8 KAKI BUKIT AVE 4

05-25 PREMIER @ KB

Singapore 415875

JTDGG20K40J005559

Accident date: 21nd April 2024

Estimated repair cost for vehicle no: SLS1424L TOYOTA WISH 1.8 AUTO '2016

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Dented</i>		<u>\$1,860.00</u> 1307
2	2	Rear Boot Lid Hinges <i>New New</i>	\$187.70	\$375.40 X
3	1	Rear boot lid emble logo <i>New</i>		\$95.00 ✓
4	1	Rear boot lid RH logo <i>New</i>		\$60.00 ✓
5	1	boot lid centre granish -wish <i>cracked</i>		\$288.00 ✓
6	1	Rear Boot Lid Inner Lock <i>Dented</i>		\$388.00 ✓
7	1	Rear boot lid inner rubber <i>ut</i>		\$276.10 ✓
8	1	boot lid keyless sensor <i>cracked</i>		<u>\$450.00</u> 162
9	1	Rear boot lid camera <i>New</i>		\$550.00 X
10	1	Rear Boot Lid top center moulding <i>Repaired</i>		\$388.00 X
11	1	Rear Boot Lid top center moulding clips -set <i>New</i>		\$50.00 +
12	1	Rear Boot Lid Number Plate <i>New</i>		\$50.00 X
13	2	Rear Boot Lid Number Plate Lamp <i>New</i>	\$135.10	\$270.20 P
14	1	Rear Boot Lid Inner Trim board <i>cracked</i>		<u>\$780.00</u> 486
15	2	Rear boot lid side reflector <i>New ut</i>	\$580.00	<u>\$1,160.00</u> 555
16	4	tail lamp clips <i>New</i>	\$8.50	\$34.00 X
17	2	tail lamp <i>New</i>	\$680.00	\$1,360.00 X
18	1	Rear End Panel <i>Repair</i>		\$880.00 X
19	1	Rear End Panel Top Garnish <i>Debond</i>		\$288.00 ✓
20	1	Rear Bumper <i>Debond</i>		<u>\$1,377.00</u> 597
21	2	Rear Bumper side reflector <i>New New</i>	\$83.10	\$166.20 X
22	2	Rear Bumper Side Bracket <i>New</i>	\$112.00	\$224.00 X
23	1	Rear Bumper reverse sensor-set <i>Dented</i>		\$350.00 + 20(SN)
24	2	Rear Bumper side retractor <i>New</i>	\$188.00	\$376.00 +
25	8	Rear bumper clips <i>New</i>	\$6.50	\$52.00 30(SN)

4502.10

Subtotal :- \$12,147.90

3376.57

S.N. 230

Labour charges

To Remove & refix cushion

~~\$120.00~~ 40

To Remove & refix reverse Sensor

~~\$120.00~~ 50

Tuff kote

~~\$120.00~~ 30

To Check Wiring System

1150

~~\$80.00~~ 30

Panel beating

~~\$800.00~~ 500

Spray painting

~~\$800.00~~ 500

Subtotal :- \$2,040.00

Total:- \$14,187.90

Total: 4756.57
H/S: 3.81c
0.5 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: