



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS ETHOZ PROTECT PTE LTD	Ref:	CS/TP24080392/Enp3e2
30 BUKIT BATOK CRESCENT SINGAPORE SINGAPORE 658075	Date:	02/10/2024
	Code:	TP513

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	-	Veh. Inspected	SMW 9831J
Policy No.	-	Coverage	0
Claim No.	-	Excess	\$0.00
Assign From	-	Assign Date	23/08/2024

2. Vehicle Details

Make & Model	AUDI A6	C.C	1984
Engine No.	DKY015720	Year of Reg.	21/02/2023
Chassis No.	WAUZZZF20MN092193	Colour	WHITE
Odometer	29356 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/55 R18	MICHELIN	5
L/H Front Tyre	225/55 R18	MICHELIN	5
R/H Rear Tyre	225/55 R18	MICHELIN	5
L/H Rear Tyre	225/55 R18	MICHELIN	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE INTERIOR.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	01/07/2024	Inspection Date	23/08/2024
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days