



55 Ubi Road 1, Singapore 408699
Tel: (65) 63662323 Fax: (65) 6841 1183
Website: www.audi.com.sg

REPAIR QUOTATION

To: Mike
Contact No: 96681342
Vehicle No: SMW9831J

Date: 29/7/2024

From: Brandon Sim

S/NO	Descriptions of Parts /Labour	Qty	Nett Price	Time By (TU)	Labour amount	Remarks
1	Diagnostic Fee	1	\$ 150.00		\$ -	/
2	Brake master pump with break servo set		\$ 2,780.50		\$ -	?
3	Floor covering with floormat set	1	\$ 4,287.00		\$ -	/ Stained by mud
4	Wiring set for Fan motor ,air con regulated	1	\$ 2,190.00		\$ -	?
5	Wiring harness for Seat frame and backrest adjustment	1	\$ 1,890.00		\$ -	?
6	Wiper motor	1	\$ 1,950.00		\$ -	/ malfunction
7	Wiring set for dash panel ,battery wiring set	1	\$ 16,280.00		\$ -	?
8	Engine control unit	1	\$ 4,650.00		\$ -	?
9	Onboard supply unit	1	\$ 4,850.00		\$ -	?
10	Driver assist unit	1	\$ 10,980.00		\$ -	?
11	Control unit for chassis	1	\$ 4,250.00		\$ -	?
12	Car battery	1	\$ 550.00		\$ -	?
13	48volt car battery	1	\$ 3,048.00			?
14	Estimate labour cost	1	\$ 6,325.00			Replaced control and wiper motor \$600
13					\$ -	
	Subtotal cost:		\$ 64,180.50	0	\$ -	

Total ala-carte parts cost:	\$ 64,180.50
Total labour cost:	\$ -
9% GST	\$ 5,776.25
Grand Total:	\$ 69,956.75

Important Note: The above repair estimate is based on an initial inspection and does not include any additional parts or labour which may be required after work has commenced. Price quoted subjects to 8% GST charges.

Validity: Quotation shown is only applicable within a month from the date of quotation.

Payment: Full payment has to be settled via Visa/ Mastercard/ Nets / Cash, upon collection of vehicle.

Authorization (Please fax back to us at 6841 1183)

I, agree to the estimate quotation shown above and hereby instruct Premium Automobiles Pte Ltd to carry out the repairs accordingly.

Signature: _____
Registered Owner/Authorized Representative

Date: _____

3 days