

ASSIGNMENT

Front: _____ Date: _____
 Estn: _____
 OD / TP RES / OD RES / EVA / INV / MV
 To In: _____ Vehicle No: _____
 at W: _____
 of _____
 Insured: _____
 Policy No: _____
 Claim: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vehicle: _____

(Policy Condition)

Remark: The vehicle had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repair: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLR2949M Yr Regn: 2017 Agust.
 Type: M. Car M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 3 C.C. 1496

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 123295 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6BN22A8H0157416

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: 205/60R16

BS / DUN / EXNOVA / GY / FS / IZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 23/08/24

Survey held at JL Persef

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP ECKS</u>
	<u>COE Expiry</u>
	<u>Estimate given during 1st Survey</u>
	<u>MV :</u>
	<u>PV :</u>
	<u>Nett :</u>
	<u>5481</u>

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

1) _____
 Date/Time, File Return to?

2) _____

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Insp (\$)

3 + RS \$1

Photos

Others

Report Format: _____

Signature of Inspector: _____

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:jlperfectautowork@gmail.com



DATE : 22.08.2024

TO : ECICS MOTOR CLAIMS DEPTS
VEHICLE NO : SLR2949M
MODEL : MAZDA 3
DATE OF ACCIDENT : 22.08.2024
TIME OF ACCIDENT : 10:50 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Replaced</i>	1	\$ 958.00	\$ 958.00
2	FRONT BUMPER (TOP) <i>Replaced</i>	1	\$ 426.00	\$ 426.00
3	FRONT BUMPER TOWING COVER <i>New</i>	1	\$ 21.60	\$ 21.60
4	FRONT BUMPER LOWER GRILLE SIDE COVER RH <i>New</i>	2	\$ 15.50	\$ 31.00
5	FRONT BUMPER FOGLAMP COVER <i>New</i>	2	\$ 74.00	\$ 148.00
6	FRONT BUMPER SIGNAL LAMP <i>New</i>	2	\$ 148.00	\$ 296.00
7	FRONT BUMPER TOP SUPPORT GARNISH <i>New</i>	1	\$ 189.20	\$ 189.20
8	FRONT BUMPER BRACKET <i>New</i>	2	\$ 49.30	\$ 98.60
9	FRONT BUMPER SIDE RETAINER <i>New RH</i>	2	\$ 27.30	\$ 54.60
10	FRONT BUMPER REINFORCEMENT <i>Replaced</i>	1	\$ 524.70	\$ 524.70
11	FRONT BUMPER REINFORCEMENT COVER GARNISH <i>New</i>	1	\$ 79.00	\$ 79.00
12	FRONT BUMPER UNDER COVER GARNISH <i>New</i>	1	\$ 88.00	\$ 88.00
13	FRONT FENDER RH <i>Replaced</i>	1	\$ 370.00	\$ 370.00
14	FRONT FENDER SUPPORT BRACKET RH <i>New</i>	1	\$ 49.00	\$ 49.00
15	FRONT FENDER INNER COWLING (FRONT) RH <i>New</i>	1	\$ 170.00	\$ 170.00
16	HEADLAMP RH <i>New</i>	1	\$ 2,357.00	\$ 2,357.00
17	HEADLAMP SUPPORT BRACKET RH <i>New</i>	1	\$ 35.20	\$ 35.20
18	FRONT GRILLE <i>New</i>	1	\$ 545.00	\$ 545.00
19	FRONT GRILLE CHROME <i>RH New</i>	2	\$ 164.00	\$ 328.00
20	FRONT GRILLE LOGO <i>New</i>	1	\$ 49.00	\$ 49.00
21	FRONT SUPPORT PANEL (TOP) <i>New</i>	1	\$ 250.00	\$ 250.00

TO : **ECICS** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLR2949M**
 MODEL : **MAZDA 3**
 DATE OF ACCIDENT : 22.08.2024
 TIME OF ACCIDENT : 10:50 HOURS

22	FRONT SUPPORT PANEL COVER GARNISH	1	\$ 143.00	\$ 143.00
23	FRONT SUPPORT PANEL LOWER GARNISH	1	\$ 89.00	\$ 89.00
24	AIR CON CONDENSER SIDE GARNISH	2	\$ 47.00	\$ 94.00
25	AIRCON CONDENSER	1	\$ 1,142.60	\$ 1,142.60
26	HORN	1	\$ 464.00	\$ 464.00
27	RADIATOR SUPPORT PANEL	1	\$ 798.00	\$ 798.00

TOTAL PRICE \$ 9,798.50
 LESS 20% \$ 1,959.70
SUB TOTAL PRICE \$ 7,838.80

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE	1	\$ 80.00	\$ 80.00
2	FRONT BUMPER CLIP (SET)	1	\$ 50.00	\$ 50.00
3	FRONT BUMPER TOP SUPPORT GARNISH CLIP (SET)	1	\$ 30.00	\$ 30.00
4	FRONT BUMPER UNDER COVER GARNISH CLIP (SET)	1	\$ 50.00	\$ 50.00
5	FRONT FENDER INNER COWLING CLIP (SET)	1	\$ 50.00	\$ 50.00
6	FRONT GRILLE CLIP (SET)	1	\$ 30.00	\$ 30.00
7	FRONT SUPPORT PANEL COVER GARNISH CLIP (SET)	1	\$ 30.00	\$ 30.00
8	FRONT SUPPORT PANEL LOWER GARNISH CLIP (SET)	1	\$ 30.00	\$ 30.00
9	FRONT SUPPORT PANEL LOWER APRON GARNISH CLIP (SET)	1	\$ 30.00	\$ 30.00
10	RADIATOR COOLANT	1	\$ 60.00	\$ 60.00

TOTAL \$ 440.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,600.00	500
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	500
3	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	X
4	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	X

TO : **ECICS** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLR2949M**
MODEL : **MAZDA 3**
DATE OF ACCIDENT : 22.08.2024
TIME OF ACCIDENT : 10:50 HOURS

5	REFOCUS HEADLAMP BEAM	\$ 60.00	x
6	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL \$ 3,440.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,278.80
TOTAL LABOUR COST : \$ 3,440.00
TOTAL REPAIR COST : \$ 11,718.80

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian
1/S 23/08/24
04 Days