

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:jlperfectautowork@gmail.com



DATE : 22.08.2024

TO : **ECICS** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLR2949M**
MODEL : **MAZDA 3**
DATE OF ACCIDENT : 22.08.2024
TIME OF ACCIDENT : 10:50 HOURS

Veron

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Distorted</i>	1	\$ 958.00	\$ 958.00
2	FRONT BUMPER (TOP) <i>Repair</i>	1	\$ 426.00	\$ 426.00
3	FRONT BUMPER TOWING COVER <i>New</i>	1	\$ 21.60	\$ 21.60
4	FRONT BUMPER LOWER GRILLE SIDE COVER RH <i>New</i>	2	\$ 15.50	\$ 31.00
5	FRONT BUMPER FOGLAMP COVER <i>cut</i>	2	\$ 74.00	\$ 148.00
6	FRONT BUMPER SIGNAL LAMP <i>combined</i>	2	\$ 148.00	\$ 296.00
7	FRONT BUMPER TOP SUPPORT GARNISH <i>New</i>	1	\$ 189.20	\$ 189.20
8	FRONT BUMPER BRACKET <i>New</i>	2	\$ 49.30	\$ 98.60
9	FRONT BUMPER SIDE RETAINER <i>Combined RH</i>	2	\$ 27.30	\$ 54.60
10	FRONT BUMPER REINFORCEMENT <i>Distorted</i>	1	\$ 524.70	\$ 524.70
11	FRONT BUMPER REINFORCEMENT COVER GARNISH <i>New</i>	1	\$ 79.00	\$ 79.00
12	FRONT BUMPER UNDER COVER GARNISH <i>New</i>	1	\$ 88.00	\$ 88.00
13	FRONT FENDER RH <i>Buckled</i>	1	\$ 370.00	\$ 370.00
14	FRONT FENDER SUPPORT BRACKET RH <i>New</i>	1	\$ 49.00	\$ 49.00
15	FRONT FENDER INNER COWLING (FRONT) RH <i>New</i>	1	\$ 170.00	\$ 170.00
16	HEADLAMP RH <i>Combined</i>	1	\$ 2,357.00	\$ 2,357.00
17	HEADLAMP SUPPORT BRACKET RH <i>New</i>	1	\$ 35.20	\$ 35.20
18	FRONT GRILLE <i>New</i>	1	\$ 545.00	\$ 545.00
19	FRONT GRILLE CHROME <i>RH cut</i>	2	\$ 164.00	\$ 328.00
20	FRONT GRILLE LOGO <i>New</i>	1	\$ 49.00	\$ 49.00
21	FRONT SUPPORT PANEL (TOP) <i>New</i>	1	\$ 250.00	\$ 250.00

TO : **ECICS** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLR2949M**
 MODEL : **MAZDA 3**
 DATE OF ACCIDENT : 22.08.2024
 TIME OF ACCIDENT : 10:50 HOURS

22	FRONT SUPPORT PANEL COVER GARNISH	1	\$ 143.00	\$ 143.00
23	FRONT SUPPORT PANEL LOWER GARNISH	1	\$ 89.00	\$ 89.00
24	AIR CON CONDENSER SIDE GARNISH	2	\$ 47.00	\$ 94.00
25	AIRCON CONDENSER	1	\$ 1,142.60	\$ 1,142.60
26	HORN	1	\$ 464.00	\$ 464.00
27	RADIATOR SUPPORT PANEL	1	\$ 798.00	\$ 798.00

4845
3876

TOTAL PRICE \$ 9,798.50
 LESS 20% \$ 1,959.70
SUB TOTAL PRICE \$ 7,838.80

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE	1	\$ 80.00	\$ 80.00
2	FRONT BUMPER CLIP (SET)	1	\$ 50.00	\$ 50.00
3	FRONT BUMPER TOP SUPPORT GARNISH CLIP (SET)	1	\$ 30.00	\$ 30.00
4	FRONT BUMPER UNDER COVER GARNISH CLIP (SET)	1	\$ 50.00	\$ 50.00
5	FRONT FENDER INNER COWLING CLIP (SET)	1	\$ 50.00	\$ 50.00
6	FRONT GRILLE CLIP (SET)	1	\$ 30.00	\$ 30.00
7	FRONT SUPPORT PANEL COVER GARNISH CLIP (SET)	1	\$ 30.00	\$ 30.00
8	FRONT SUPPORT PANEL LOWER GARNISH CLIP (SET)	1	\$ 30.00	\$ 30.00
9	FRONT SUPPORT PANEL LOWER APRON GARNISH CLIP (SET)	1	\$ 30.00	\$ 30.00
10	RADIATOR COOLANT	1	\$ 60.00	\$ 60.00

TOTAL \$ 440.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,600.00	550
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	500
3	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	X
4	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	X

TO : **ECICS** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLR2949M**
MODEL : **MAZDA 3**
DATE OF ACCIDENT : 22.08.2024
TIME OF ACCIDENT : 10:50 HOURS

5	REFOCUS HEADLAMP BEAM	\$ 60.00	60 30
6	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	+

1080

TOTAL \$ 3,440.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,278.80
TOTAL LABOUR COST : \$ 3,440.00
TOTAL REPAIR COST : \$ 11,718.80

Adrian
h/s 23/08/24
04 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

total: 5006
h/s: 4k ✓

<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
