

Vehicle:

GBL80G

Make & Model:

TOYOTA HIACE

Chassis No:

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend
1	Right Silding Door			\$ 1,840.70	R X
2	Right Rear Fender			\$ 1,545.40	R X
3	Rear Bumper			\$ 768.50	groked ✓
4	Rear Bumper Clips			\$ 30.00 SN	ner ✓ s/n
5	Rear Bumper Retainer (Right)			\$ 141.50	11 X
6	Right Rear Rim			\$ 180.00 SN	R X
7					252
	Labour				
1	Anti Rust Proof			\$ 60.00	11 X
2	Panel Beating			\$ 900.00	800
3	Paint work			\$ 800.00	500

STYTECH AUTO PTE. LTD.

2 Kaki Bukit Ave 2 #01-03
Kaki Bukit Autohub Singapore 417921
Tel: 6444 8125 Fax: 6445 3310
GST Reg. No.: 201601539K
Co. Reg. No.: 201601539K

Not Authorized
ner
26/8/24
2/5 & 1500/
H by s.
John ph. 110.21

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2,768.50
252
57638
30
1300
190638
252
1525