SPEEDWERKZ PRIVATE LIMITED

1 KAKI BUKIT AVENUE 6 #01-73, AUTOBAY, SINGAPORE 417883

Tel: 96195936 / info@speedwerkz.biz

VEHICLE NUMBER: SLV1771T

MAKE & MODEL: MERCEDES BENZ GLC200

4 (,		
TAILGATE BOND PO		\$2,788.60
TAILGATE LOGO NU		\$61.06 /
TAILGATE GLC200 EMBLEM New KIV		\$98.30 🗶
TAILGATE LAMP L/R X2 NIS CAO US AA	511.43	\$1,316.80 126
TAILGATE WEATHERSTRIPE		\$486.10 ×
TAILGATE INNER LOCK Days.		\$322.10
TAILGATE LOCK STRIKER		\$48.90 ×
TAILGATE NUMBER PLATE LAMP L/R 🗚		\$322.60 头
TAILGATE WIPER MOTOR 41		\$711.30 >
TAILGATE WIPER ARM		\$135.60 ×
TAILGATE OUTER LOCK SWITCH A		\$265.80 🗴
TAILGATE INNER TRIMBOARD CM7 /TW1	645.31	\$857.30
REAR WINDSCREEN GLASS BND	1322.51	\$1,512.70
TAIL LAMP ALS	822.00	\$1,388.60
REAR BUMPER	0.700	\$1,455.20 ×
REAR BUMPER LOWER Yeak ground	545.N	\$655.10
REAR BUMPER LOWER CHROME CAL	481.20	\$513.70
REAR BUMPER LOWER EXHAUST CHROME L/R X2 4 1	14170	\$886.80 X
REAR BUMPER TOW COVER 1		\$87.02 🗸
REAR BUMPER UNDER COVER 1		\$373.30x
REAR BUMPER SIDE RETAINER L/R X2 11		\$196.80X
REAR BUMPER SIDE BRACKET L/R X2 ^1		\$294.60
REAR BUMPER REFLECTOR L/R X2		\$96.80 %
REAR BUMPER SWITCH MODULE ^^		\$386.66 X
REAR BUMPER SWITCH MODULE BRACKET 🔥 🥎		\$88.10 🗶
REAR BUMPER SWITCH MODULE CODE-A 17		\$189.60 🗙
REAR BUMPER SWITCH MODULE CODE-B		\$189.60 ×
REAR BUMPER REINFORCEMENT R		\$810.50
REAR BUMPER CENTRE MOUNT BRACKET 1		\$201.30 ×
REAR BUMPER REVERSE SENSOR X4		\$1,010.40 ×
REAR BUMPER REVERSE SENSOR BRACKET SET $\ \ $		\$48.00 /
END PANEL A		\$1,625.70
END PANEL GARNISH A	_	\$585.10
		\$20,010.04
	Less 10%	\$2,001.00
		\$18,009.04
REAR BUMPER CLIPS $\Lambda \gamma$		\$100.00 X
REAR BUMPER RIVET		\$80.00 🗴
TAILGATE INNER TRIMBOARD CLIPS ALL		\$65.00 570
TAILGATE WIPER BLADE \(\sigma \sigma \)		\$140.00 🗶

Not Authorial
mercans
23/8/24
d/4 7000
which Affara

TAILGATE C&C LOGO ARC KIV	\$88.00 X
REAR WINDSCREEN GLASS SEALANT 1/2	\$80.00 40
REAR WINDSCREEN GLASS SPONGE 1.20	\$60.00 22
REAR WINDSCREEN GLASS TINT FILM LLL	\$450.00 / 87
END PANEL GARNISH CLIPS	\$50.00 💉
END PANEL SEALANT	\$80.00 🕱
REAR NUMBER PLATE WITH GARNISH \$4, ₹	\$60.00 40
	\$1,253.00
TO CHEÇK REAR WIRING	\$50.00 20
TO REPLACE REAR REVERSE SENSOR	\$120.00 30
TO REPLACE REAR REVERSE CAMERA	11 \$150.00X
TO REMOVE AND TRANSFER TAILGATE FITTINGS TO NEW	\$250.00 60
TO REMOVE AND REFIT REAR INTERIOR TRIMS	17 \$200.00 X
TO PROVIDE LABOUR, WORKMANSHIP	\$2,000.00 540
TO SPRAY PAINT ON AFFECTED PANELS	\$2,000.00 <i>80</i> 0
TO REPROGRAMME AND CALIBRATE PARKING SENSORS & CAMERA	\$300.00
TO REPROGRAMME AND CALIBRATE TAILGATE FUNCTION	\$150.00
TO REPLACE REAR WINDSCREEN GLASS	\$200.00 / 20
TO VACUUM AND CLEAN INTERIOR FOR GLASS SHARDS	ハヘ \$250.00 火 \$180.00 ろひ
RUST PROOFING	\$5,850.00
	المان دور د د
Total	\$25,112.04

LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before/after spray painting

To display damaged part(s) during resurvey

Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

P-7499.42 102 6749.48 330 1680-2789.48 22 7007.