

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 11 Sep 2024

**Preliminary Advice**

Insured Vehicle No	: SMN5608L	Accident Date	: 22/08/2024
TP Vehicle No	: SLB7613H	Assignment Date	: 23/08/2024
Make	: NISSAN QASHQAI	Est. Duration of Repair	: 6
Date of Inspection	: 23/08/2024		
Inspection At	: FASTECH AUTO PTE LTD (HQ) 1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	37,389.57
Revised Amount	:S\$	12,311.80
Check Items (Estimated)	:S\$	0.00
Total	:S\$	12,311.80
 Lump Sum Repair	 :S\$	 9,800.00

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical for repair  
 ( ) The vehicle is not economical for repair  
 ( ) Part-by-Part repair  
 ( x ) Lump Sum repair
- ( x ) The above survey was conducted on a 'without prejudice' basis.  
 Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.