

(08/11/13) Wef

ASS. REC. BY:

REF: CS/FC124080398/Rap3


231E

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SMA 373P
 at Workshop m/s PERFORMANCE
 of ALEXANDRA RD
 Insured: PCI 2
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: 132K
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMA 373P Yr Regn: 2023 MAR
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: B.M.W 216I A TMSPT c.c. 1499
 Colour: GREEN AC: Insured / Std / NI / NA
 Sp. Reading: 29120 T/Radio: Insured / Std / NI / NA
 Eng/No: _____

C/No: WBA12BX0067M06459Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50R18
 R: _____

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

CONTINENTAL

Front

R/Bal. 6 mm

Rear

R/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 18/08/24D.O.I. 30/08/24

Survey held at

ALEXANDRADes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orREAR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 22K

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

1) _____
 Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

) S + RS \$

) Photos

) Others

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$))

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

→ ms FC1
22 Aug 2024

Estimate No. : b1 70956
Date Estimated : 22/08/2024
Prepared By : Tee Hong Da

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Khoo Teng Jin
10 Greenwood Crescent

Singapore 286976

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMA373P	WBA12BX0007M06459	31/03/2023	216i Active Tourer	27118

DESCRIPTION

To replace rear bumper and attachment

To respray rear bumper and attachment

To check electrical wiring system and lighting at the rear section for proper function.

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

Sundries.

Pass

Hp 9001068

3 days

30/08/24

Repr 54 part

VALUE

850 1,700.00

2,076.00

177.00

177.00

? 150.00

Total Labour 1: 4,280.00

DESCRIPTION

REAR BUMPER PANEL PRIMED *de*
REAR BUMPER BOTTOM TRIM PANEL *repr*
LH FINISHER *repr*
REAR BUMPER CARRIER ?
Ultrasonic
DECOUPING RING PDC TORQUE CONVERTER *re*

QTY	PRIC	VALUE
1	905.95	905.95
1	215.70	215.70
1	57.90	57.90
1	500.75	500.75
2	403.40	806.80
2	5.65	11.30

Total Parts : 2,498.40



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and

Labour 1	:	4,280.00
Parts	:	2,498.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 9%	:	610.06
Grand Total	:	7,388.46

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE **

Acknowledged by Repairer

Signature

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	231E
Vehicle Details	
Vehicle No.:	SMA373P
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Sep 2024
Vehicle Make:	B.M.W.
Vehicle Model:	216i ACTIVE TOURER MSPT ALED
Primary Colour:	Green
Manufacturing Year:	2023
Engine No.:	F192P297B38A15P
Chassis No.:	WBA12BX0007M06459
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$33,206.00
Original Registration Date:	31 Mar 2023
First Registration Date:	31 Mar 2023
Transfer Count:	0
Actual ARF Paid:	\$38,489.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Mar 2033
PARF Rebate Amount:	\$28,866.00
Intended COE Rebate Details	
COE Expiry Date:	30 Mar 2033
COE Category:	A - Car-Details at OneMotoring
COE Period(Years):	10
QP Paid:	\$93,503.00
COE Rebate Amount:	\$80,206.00
Total Rebate Amount:	\$109,072.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 01 Sep 2024

OK



BMW 2 Series 216i Active Tourer M-Sport

\$99,800 Instalment \$1,253/mth

 This car is eligible for [Sgcarmart Warranty](#)

 Apply for 2.48% loan

 Shortlist

 Loan Calculator



Overview Financial Photo Research

Depreciation	 \$15,400 / year
Reg. Date	16-Jan-2020 (5yrs 4mths 14days COE left)
Manufactured	 2019
Mileage	68,000 km (14.7k / year)
Transmission	Auto
Engine Cap	1,499 cc
Road Tax	 \$684 / year
Power	80.0 kW (107 bhp) View specs of the BMW 2 Series Active Tourer (2014-2021)
Curb Weight	 1,380 kg
COE	 \$35,320
OMV	 \$30,044
ARF	 \$34,062