

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS24080399/KVP3E2
Date: 09/09/2024

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SMP1130M	Insured Vehicle No :	SNQ8395C
Date of Loss:	28/07/2024	Nature of Claim:	TP
		Claim No:	DMPC2400977H/02/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP1130M	Engine No:	LEB7109780
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Chassis No:	GP72007813
Reg. Date:	11/09/2019 (Man. Year: 2019)	Odometer:	233324 km
Colour:	Metallic Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Firenza 9 mm	Rear Left Side:	Firenza 9 mm
Front Right Side:	Firenza 9 mm	Rear Right Side:	Firenza 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,659.72	2,080.76	578.96	21.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,370.00	920.00	450.00	32.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,029.72	3,000.76	1,028.96	25.53
Approved Total (Overridden) (S\$)		2,400.00		
(S\$)	4,029.72	2,400.00	1,629.72	40.44
+ GST 9.00/9.00% (S\$)	362.67	216.00	146.67	40.44
Nett Amount (S\$)	4,392.39	2,616.00	1,776.39	40.44

INSPECTION

Date of Assignment:	23/08/2024		
Date Inspected:	26/08/2024	Inspected At:	City Auto Pte Ltd (HQ) 160 Sin Ming Drive #05-01,, Sin Ming AutoCity, Singapore 575722
Estimated Period of Repair:	4.0 days		

Adjuster: KENNETH KONG Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 09 Sep 2024)	
Parts:	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP1130M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,293.20 FL	*1,193.20 FL
2	1		*TAILGATE EMBLEM - HYBRID	Necessary	88.10 FL	*88.10 FL
3	1		*TAILGATE EMBLEM - SHUTTLE	Necessary	65.60 FL	*65.60 FL
4	1		*WEATHER STRIP	Serviceable	168.50 FL	*- FL
5	1		*LOCK	Repair	178.20 FL	*- FL
6	2		*REAR BUMPER SIDE RETAINER	Serviceable	77.00 FL	*- FL
7	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	97.20 FL	*97.20 FL
8	1		*NUMBER PLATE	Scratched	20.00 FS	*20.00 FS
9	1		*NUMBER PLATE CASING	Scratched	25.00 FS	*25.00 FS
10	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
11	1		*REAR BUMPER	Buckled	1,250.60 FL	*1,050.60 FL
						F=Franchise part. S=SpcNett. L=ListItemDisc.
Sub Total (S\$)					3,303.40	2,579.70
- List Item Discount on L Items 20.00/20.00% (S\$)					643.68	498.94
Total Parts (S\$)					2,659.72	2,080.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	120.00	120.00
2	TO KNOCK JACKOUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ACCIDENT PARTS	New	500.00	400.00
3	SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	750.00	400.00
Gross Labour Cost (\$\$)			1,370.00	920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >