

ASS. REC. BY:

REF:

167/CS/SMR24080400/Kgp3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

Optim

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$36k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

PMP 2207U

Yr Regn:

11.11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

M

S300L

C.C

2PPF

Colour

M. Black

AC:

Insured / Std / NI / NA

Sp. Reading

247092

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD 2211542A 434904

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

255/40R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

8 mm

R/Bal.

8 mm

L/Bal.

8 mm

L/Bal.

8 mm

D.O.A.

14/8/24

D.O.I.

26/8/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

5/9 11/11/24 @ 3350/ Car in U/C to 2454, 42%

Date/Time, File Pass to?

☐

: Prell. Report

1) 09/9/24

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

2

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.A. (\$

TP

3350

TOTAL

Date: 19-8-2024
Vehicle No: SMP2207U
Model: MERCEDES BENZ S300L
Chassis: WDD2211542A434904
Reg.Year: 24.11.2011

*Not withholder
61 days 83350/h
2 days*

Third Party Insurer: FCIL
Third Party Veh No: SHB5813H
Date of Accident: 14/08/2024
Estimator: Loong
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1		CNA \$2,100.00
2	REAR REVERSE SENSOR	2	\$300.00	\$600.00
3	REAR LH BUMPER RETAINER	1		PL \$110.00
4	REAR BUMPER REINFORCEMENT	1		RY \$850.00
5	REAR END PANEL	1		REPAIR
6	REAR BOOT	1		REPAIR
SUB TOTAL				\$3,660.00
LESS 10%				-\$366.00
PARTS TOTAL				\$3,294.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		RM \$50.00
2	REAR REVERSE SENSOR MOUNTING BRACKET	1		RM \$350.00
S/N TOTAL				\$400.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

22d \$600.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOT, REAR BUMPER, REAR END PANEL & ETC.

25d \$800.00

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

\$100.00 60d

TO DIAGNOSTIC AND RESET RADAR SENSOR FAULT CODE

RM \$250.00 X

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$100.00 15d

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

LABOUR TOTAL \$1,850.00

TOTAL \$5,544.00

Acknowledged by Repairer

Signature:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 3 Singapore 554500
Tel: (+65) 6484 9919 Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 Fax: (+65) 6481 1011



Date: 3-9-2024
 Vehicle No: SMP2207U
 Model: MERCEDES BENZ S300L
 Chassis: WDD2211542A434904
 Reg.Year: 24.11.2011

Third Party Insurer: FCIL
 Third Party Veh No: SHB5813H
 Date of Accident: 14/08/2024
 Estimator: Loong
 Surveyor:

SUPPLEMENTARY ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR LH BOOT SILL COVER	1	my car	\$100.00
2	REAR RH BOOT SILL COVER	1	2	\$100.00
SUB TOTAL				\$200.00
LESS 10%				-\$20.00
PARTS TOTAL				\$180.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BOOT SILL COVER CLIPS SET	1		\$80.00
S/N TOTAL				\$80.00

Finalise:

Parts = \$ 3375.00
 Nett = \$ 280.00
 Labor = \$ 545.00

Insurance = \$ 4200.00 -20%
 = \$ 3360.00 ⇒ \$ 3400.00

Head office

8 Kung Chong Road Singapore 159143
 Tel: (+65) 5472 1313 | Fax: (+65) 5472 2112

Branch

3A Serangoon North Ave 5 Singapore 554800
 Tel: (+65) 6484 0019 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 569047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



[➤ Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	105E

Vehicle Details

Vehicle No.:	SMP2207U
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Aug 2024
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	S300L
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	27294631962435
Chassis No.:	WDD2211542A434904
Maximum Power Output:	170.0 kW (227 bhp)
Open Market Value:	\$85,329.00
Original Registration Date:	24 Nov 2011
First Registration Date:	24 Nov 2011
Transfer Count:	5
Actual ARF Paid:	\$85,329.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	30 Sep 2026
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$29,062.00
COE Rebate Amount:	\$12,351.00
Total Rebate Amount:	\$12,351.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be deregistered once the COE expires, or when it reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 15 Aug 2024

OK