

LEANG AUTOMOTIVE
BLK 1 KAKI BIKIT AVE 6 #01-68
AUTOBAY S'PORE 417883 HP 90286516

not Authorized
20/6/24
1/5 \$ 2050 /
3 days
Stephen Henry
NETT ITEM

VEHICLE No: SKT 8613T

1PC	BONNET		\$1,014.10 X
1PC	FRONT BUMPER	R cut/de	\$822.90 ✓
2PCS	FRONT BUMPER SIDE RETAINERS @\$45.00	11	\$90.00 X
1PC	FRONT BUMPER SPONGE	11	\$166.60 X
1PC	FRONT BUMPER REINFORCEMENT	11	\$422.10 X
1SET	FRONT BUMPER CLIPS	11	\$35.00 X
1PC	FRONT GRILLE	scr	\$322.80 ✓
1PC	FRONT LICENCE PLATE W/HOLDER	scr	\$42.00 ✓
1PC	HEADLAMP O/S	scr	\$905.00 ✓
1PC	FRONT FENDER O/S	11	\$711.20 X
			\$4,531.70
LESS 10%			\$4,078.53

TO CHECK WIRING	\$50.00 20
TO SPRAY RUST PROOFING	11 \$50.00 X
TO REFILL AIR CON GAS	11 \$100.00 X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$680.00 300
TO PUTTY & SPRAY PAINTING	\$1,080.00 400
TOTAL	\$6,038.53

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

p- 2092.7
102
1883.43
720
2603.43
202
2081.