



ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Repair Estimates

SNR 9475 T

Parts	(a) Cost / List Price Items	\$	2,109.00
	Plus/Less 10%	\$	210.90
	Total of Cost / List	\$	1,898.10
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	200.00
Total Parts Cost		\$	2,098.10
Labour		\$	1,420.00
Total		\$	3,518.10

*Not to be taken
Running B4 paint
@ 1406-20*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 9% G.S.T.

Name of Surveyor : Kenneth
Company : 2K1C
Survey conducted on : 26/8/24 at _____

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 03 day(s)

(c) Resurvey : Required / Not Required Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Le Date: 26/8/24

**ESTEEM**ESTEEM PERFORMANCE PTE LTD
UEN 200005485NHEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829**Spare Parts**Vehicle No. : **SNR 9475 T**
Make & Model : **KIA NIRO**
Chassis No : **KNACP81EVR5178169**Submit By : **LI HONG**
Year Manufacture : **2024 JUL**
Engine No. :**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor <i>Sn</i>	2	\$200.00	S.N	X
2	Rear bumper <i>R</i>	1	\$566.00		X
3	Rear bumper clip <i>Sn</i>	10	\$35.00		✓
4	Rear bumper side retainer LH <i>Sn</i>	1	\$43.00		X
5	Rear bumper side retainer RH <i>Sn</i>	1	\$43.00		X
6	Rear bumper bracket LH <i>R</i>	1	\$12.00		X
7	Rear bumper bracket RH <i>R</i>	1	\$12.00		X
8	Rear bumper reinforcement <i>R</i>	1	\$281.00		X
9	Rear bumper lower garnish <i>Sn</i>	1	\$494.00		✓
10	Rear bumper reflector RH <i>Sn</i>	1	\$384.00		X
11	RH rear fender protector <i>Sn</i>	1	\$189.00		✓
12	RH rear fender protector clip <i>Sn</i>	10	\$50.00		✓
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14 , #01-15 , #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Vehicle No.	: <u>SNR 9475 T</u>	Submit By	: <u>LI HONG</u>
Make & Model	: KIA NIRO	Year of Manufacture	: 2024 JUL

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.