

ASS. REC. BY:

REF:

CO/SNR 24080401/Kgp3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

03 days

Res.: Yes or No

Lum Sum:

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNR 94757

Yr Regn:

07, 24

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kia

Niro

C.C.

1580

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

8956

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KNACP81EUR5178169

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kumho

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

23/8/24

D.O.I.

26/8/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

9/9 21:00 @ 1406.20 Calm (Red to 21140, 60%)

Date/Time, File Pass to?

☐

Prel. Report

1) 09/9 1406.20

☐

Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I.: (\$

7P

1406.20

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fees:

Others:

TOTAL

**ESTEEM****ESTEEM PERFORMANCE PTE LTD**
UEN 200005485N**HEADQUARTERS / SHOWROOM / WORKSHOP**
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394**WORKSHOP**
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829**Repair Estimates**

SNR 9475 T

Parts	(a) Cost / List Price Items	\$	2,109.00
	Plus/Less 10%	\$	210.90
	Total of Cost / List	\$	<u>1,898.10</u>
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	200.00
Total Parts Cost		\$	<u>2,098.10</u>
Labour		\$	<u>1,420.00</u>
Total		\$	<u>3,518.10</u>

Not Authorized
Penny Bypain
@ 1406.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 9% G.S.T.

Name of Surveyor : Kenneth
Company : 2K1C
Survey conducted on : 26/8/24 at _____

Remarks By Surveyor(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.(b) Recommended Days of Repair : 03 day(s)(c) Resurvey : Required / Not Required Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Le Date: 26/8/24

**ESTEEM**

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Spare Parts

Vehicle No. : **SNR 9475 T**
Make & Model : **KIA NIRO**
Chassis No : **KNACP81EVR5178169**

Submit By : **LI HONG**
Year Manufacture : **2024 JUL**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	2	\$200.00	S.N	X
2	Rear bumper	1	\$566.00		X
3	Rear bumper clip	10	\$35.00		✓
4	Rear bumper side retainer LH	1	\$43.00		X
5	Rear bumper side retainer RH	1	\$43.00		X
6	Rear bumper bracket LH	1	\$12.00		X
7	Rear bumper bracket RH	1	\$12.00		X
8	Rear bumper reinforcement	1	\$281.00		X
9	Rear bumper lower garnish	1	\$494.00		✓
10	Rear bumper reflector RH	1	\$384.00		X
11	RH rear fender protector	1	\$189.00		✓
12	RH rear fender protector clip	10	\$50.00		✓
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14 , #01-15 , #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.