

BLUWEL AUTOMOTIVE SERVICE PTE LTD
 1 KAKI BUKIT AVE 6 # 01-28/55
 SINGAPORE 417883

*Not Allowed
 as
 more
 23/8/24
 2/5 \$5600
 6 days*

VEHICLE No: SMM 4730C

1PC	REAR WINDSCREEN	11	\$1,488.10	X
1PC	REAR WINDSCREEN MOULDING	neu	\$148.30	/
1PC	TAILGATE	Body 00	\$1,602.20	/
1PC	TAILGATE REAR LOGO	neu	\$68.50	/
1PC	TAILGATE 'SIENTA' EMBLEM	neu	\$76.80	/
1PC	TAILGATE 'V' EMBLEM	neu	\$68.00	/
2PCS	TAILGATE REFLECTORS @\$413.00	11	\$826.00	X
1PC	TAILGATE WEATHERSTRIP	1W	\$357.00	/
1PC	TAILGATE INNER LOCK	3 set/1W	\$489.80	/
1PC	TAILGATE LOCK STIRKER	11	\$60.00	X
1PC	REAR BUMPER	Torn	\$522.30	/
1PC	REAR BUMPER CENTRE BLACK GARNISH	ground	\$386.70	/
1PC	REAR BUMPER REFLECTOR	CNA	\$75.20	/
2PCS	REAR BUMPER SIDE BLACK GARNISHS @\$195.50	N/S 110/5 2e	\$391.00	1PC
1PC	REAR BUMPER LAMP CENTRE	11	\$335.20	X
1PC	REAR BUMPER SIDE RETAINER N/S	11	\$130.00	X
2PCS	REAR BUMPER PDC SENSORS @\$285.00	malfunction	\$570.00	/
1PC	REAR END PANEL OUTER	10/1W	\$699.10	/
1PC	REAR END PANEL INNER	R	\$559.10	X
1PC	REAR ANTENNA SENSOR	neu	\$350.00	/
1PC	REAR END PANEL TOP GARNISH	1W1	\$268.90	/
2PCS	TAILLAMPS @\$650.50	11	\$1,301.00	X
2PCS	TAILLAMP HOUSING PANELS @\$650.30	R	\$1,300.60	X
1PC	REAR FENDER	R	\$1,205.10	X
1PC	REAR FENDER INNER TRIM BOARD N/S	11	\$870.20	X
1PC	REAR FLOOR PANEL	R	\$1,415.10	X
1PC	REAR FLOOR PANEL TOP BOARD	11	\$622.30	X
			\$16,186.50	
			LESS 25%	\$12,139.88

S.NETT

1SET	REAR BUMPER CLIPS	neu	\$50.00	✓
1PC	REAR WINDSCREEN SEALANT	neu	\$50.00	40
1PC	REAR WINDSCREEN INNER SEAL	neu	\$50.00	20
1PC	REAR END PANEL SEALANT	neu	\$50.00	✓
1SET	TAILGATE INNER TRIM CLIPS	neu	\$50.00	✓
1SET	REAR FLOOR PANEL INSULATOR	11	\$450.00	X
	TO CHECK WIRING		\$50.00	20
	TO DISMANTLE & REPLACED REAR PDC SENSOR		\$80.00	30
	TO DISMANTLE & REFIX REAR WINDSCREEN		\$150.00	120

TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00 80
TO RESET & REPROGRAMME DIAGNOSIS SYSTEM	\$100.00 80
TO DISMANTLE & REFIX REAR EXHAUST	11 \$100.00 X
TO TRANSFER TAILGATE MECHANISM	\$100.00 60
TO SPRAY PROOFING	\$180.00 60
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,200.00 850
TO PUTTY & SPRAY PAINTING	\$1,500.00 1100
TOTAL	\$16,419.88

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, when resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

7-5878.30
252
4408.73
710
2400
7018.73
203
5614