



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS BLUWEL AUTOMOTIVE SERVICE PTE LTD		Ref:	CS/TP24080403/Uqp3m4	
BLK 1 KAKI BUKIT AVE 6		Date:	09/09/2024	
#01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883 ON		Code:	TP149	
BEHALF OF JIANG BIN				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	-	Veh. Inspected	SLU 9507T	
Policy No.	-	Coverage	0	
Claim No.	-	Excess	\$0.00	
Assign From	-	Assign Date	23/08/2024	
2. Vehicle Details				
Make & Model	MERCEDES BENZ A180 (A)	C.C	1595	
Engine No.	27091031456592	Year of Reg.	19/12/2017	
Chassis No.	WDD1760422J691492	Colour	BLUE	
Odometer	52467 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	GOOD	
Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	225/45R17	MICHELIN	6	
L/H Front Tyre	225/45R17	MICHELIN	6	
R/H Rear Tyre	225/45R17	MICHELIN	6	
L/H Rear Tyre	225/45R17	MICHELIN	6	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/08/2024	Inspection Date	23/08/2024	
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				